

**Inspection Photos**  
**Location Name: EDKAM #2-23 corrective action**  
**API: 05-123-11885**



**Separator is not anchored.**



**Earth berm is inadequate.**