

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:
09/17/2018
Submitted Date:
09/18/2018
Document Number:
689401622

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: CONKLIN, CURTIS On-Site Inspection
312550 _____ 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
OGCC Operator Number: 53255
Name of Operator: MARALEX RESOURCES INC
Address: P O BOX 338
City: IGNACIO State: CO Zip: 81137

Findings:
12 Number of Comments
2 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Reid, Jordan	(970) 563-4000	maralextechjr@gmail.com	All Inspections
Graves, Jim	(970) 858-8550	mrinc20@qwestoffice.net	Operation Manager
Hartman, Robert	(970) 244-3041	bhartman@blm.gov	Petroleum Engineer
Engineering		dnr_cogccengineering@state.co.us	All Engineering
O'Hare, Mickey	(970) 563-4000/ (719) 429-3529	amohare@maralexinc.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
221894	WELL	SI	07/01/1982	GW	077-08496	USA 1-5MR	TA

General Comment:
[This is a follow up inspection to FIR Doc#689401076. Any corrective actions not addressed from previous inspections are still applicable. This well is listed on AOC 1V-609](#)

Location

Lease Road:			
Type	Access		
comment:	Access via BLM road.		
Corrective ActionL			Date:

Overall Good:

Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:

Emergency Contact Number:			
Comment:	Posted Emergency Contact Number 1-970-858-8550		
Corrective Action:			Date:

Good Housekeeping:			
Type	OTHER		
Comment:	Vegetation around wellhead.		
Corrective Action:	Comply with Rule 603.f .		Date: 01/18/2019

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	PIT		
Comment:	Wildlife fence		
Corrective Action:			Date:

Venting:			
Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected Facilities

Facility ID: 221894 Type: WELL API Number: 077-08496 Status: SI Insp. Status: TA

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment: Production records show well has been shut in since January 1999. No production equipment on site. No MIT on file. Form 4 Doc#401175092 approved 1/5/17 for TA status. COA States: "Approval of this Sundry fulfills condition number 11 of Maralex ACO 1V-609. Per Rule 319 b.(1) Maralex will need to submit annual sundry notice for continued temporary abandonment stating the method by which the well is closed to the atmosphere and plans for future operation." No current Form 4 on file.

Corrective Action: A Sundry Notice, Form 4, shall be submitted annually stating the method the well is closed to the atmosphere and plans for future operation.

Date: 03/27/2018

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: _____ Lined: NO Pit ID: 116437 Lat: 39.133722 Long: -108.367211

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: _____ Liner Condition: _____

Comment:

Corrective Action

Date: _____

Fencing:

Fencing Type: Wildlife Fencing Condition: Adequate

Comment:

Corrective Action

Date: _____

Netting:

Netting Type: _____ Netting Condition: _____

Comment:

Corrective Action

Date: _____

Anchor Trench Present: _____ Oil Accumulation: NO 2+ feet Freeboard: _____

Comment: Pit was dry at time of inspection with vegetation established in and around it.

Corrective Action

Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401766312	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581585
689401623	USA 1-5MR Follow up photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4581581