

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #1

Smuggler 16-10-62 (API # 05-123-31853) wellhead

Stained soil, weeds

Bradenhead not plumbed to surface



Photo #2

Smuggler 16-10-62 Battery

Weeds

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #3
Smuggler 16-10-62 gas engine
Stained soil
From previous FIR



Photo #4
Smuggler 16-10-62 gas engine
Stained soil

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #5
Smuggler 16-10-62 engine exhaust
Stained soil
From previous FIR



Photo #6
Smuggler 16-10-62 engine exhaust
Stained soil

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #7
Smuggler 16-10-62 Tanks
Weeds



Photo #8
Smuggler 16-10-62 Treater
Weeds

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #9
Smuggler 16-10-62 Engine House
Open bucket – Oily waste




Photo #10
Smuggler 16-10-62 Treater house
Unmarked riser

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #11

Smuggler 16-10-62 Produced H2O tank

No capacity posted

From previous FIR



Photo #12

Smuggler 16-10-62 Produced H2O tank

Capacity posted

Inspection Photos

Location Name: Smuggler /16-10-62

Location #: 418211



Photo #13

Smuggler 16-10-62 Crude oil tank

No capacity posted

From previous FIR



Photo #14

Smuggler 16-10-62 Crude oil tank

Capacity posted



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos
Location Name: Smuggler /16-10-62
Location #: 418211



Photo #15
Smuggler 16-10-62 Candlestick Flare
Not in operation
Not flaring or venting



Photo #16
Smuggler 16-10-62 Candlestick Flare
Flare inlet - Closed