

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2018

Submitted Date:

09/25/2018

Document Number:

681701091**FIELD INSPECTION FORM**Loc ID 335163 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒
- THIS IS A FOLLOW UP INSPECTION
-
- ☐
- FOLLOW UP INSPECTION REQUIRED
-
- ☐
- NO FOLLOW UP INSPECTION REQUIRED

Findings:4 Number of Comments1 Number of Corrective Actions

- ☒
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Fischer, Alex		alex.fischer@state.co.us	
Spencer, Stan		stan.spencer@state.co.us	
Holtz, Darin		darin.holtz@state.co.us	
,		COGCC.inspections@caerus oilandgas.com	All Inspections
Leonard, Mike		mike.leonard@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278820	WELL	PR	02/19/2009	GW	045-10952	GMU 23-14 (C26NW)	EI

General Comment:[COGCC Environmental Inspection. Follow-up to eForm 22 Accident Report doc #401772600.](#)

[Operator was on site with vac truck to remove impacted material from inside of tank berms. Met with Operator \(R. Hager\) to discuss fire that occurred while tank was being prepared for cleaning on 9/21/2018 \(see Accident Report for additional information\). Extent of fire was limited to tank at SE corner of tank battery, though battery liner was damaged in fire. See photos. Operator indicated plans to repair liner and remove damaged tank.](#)

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,

Comment: Fire reported to COGCC started at access panel of heated condensate AST at SE corner of tank battery. See photos. Fire was contained to bottom portion of tank.

Corrective Action: Date: **Paint**Condition: Other (Content) Other (Capacity) Other (Type) **Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Insufficient	Base Insufficient	Inadequate

Comment: Tank battery liner was compromised in the fire.

Corrective Action: Inspect entire secondary containment for integrity. Repair or install berms or other secondary containment devices per Rule 605.a.(4).

Date: 10/25/2018

Venting:

Yes/No	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Flaring:

Type	<input type="text"/>		
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>	Date:	<input type="text"/>

Inspected FacilitiesFacility ID: 278820 Type: WELL API Number: 045-10952 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
681701092	20180925 field photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4588254