

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/25/2018

Submitted Date:

09/25/2018

Document Number:

691200492

**FIELD INSPECTION FORM**

Loc ID 306260 Inspector Name: Evins, Bret On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 100322  
Name of Operator: NOBLE ENERGY INC  
Address: 1001 NOBLE ENERGY WAY  
City: HOUSTON State: TX Zip: 77070

**Findings:**

- 12 Number of Comments
- 4 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	<a href="#">Integrity Engineer Tech</a>
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>
Pesicka, Conor		conor.pesicka@state.co.us	
		dnr_cogccengineering@state. co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
287412	WELL	SI	04/01/2016	OW	123-24320	BASHOR PC AA17-23	SI

**General Comment:**

This is a WELL inspection. For Battery information refer to FIR #691200490 dated 9/25/2018. Observed leaking gas at wellhead casinghead. Dry vapor only. No fluid observed. Attempted to contact Noble by phone. Both numbers posted on well sign were NOT accurate. { 970-785-5000 & 970-939-8585 }. Was able to reach Noble at another number 970-304-5000 at 2:54 pm. Advised Ray from Operations dispatch of the leak. He advised that an operator would be sent to location. Operator JD arrived on scene approximately 3:30 pm. He advised that the route operator had discovered this leak yesterday 9/24/2018 and reported it. No further action regarding this leak at this time.

Location			
<b>Lease Road:</b>			
Type	Access		
comment:	Adequate		
Corrective Action:		Date:	
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Phone numbers posted at well are NOT accurate. Refer to Rule 210.b for guidance. (30 days).		
Corrective Action:	Post accurate phone number at well. Comply with Rule 210.b.	Date:	10/25/2018
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
<b>Emergency Contact Number:</b>			
Comment:	Emergency contact number at well is NOT accurate. Refer to Rule 210.b for guidance. (30 days).		
Corrective Action:	Post accurate emergency phone number at well. Comply with Rule 210.b.	Date:	10/25/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment: <input style="width: 100%;" type="text"/>			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Iron panel.		
Corrective Action:		Date:	
<b>Equipment:</b>			
Type:	#		corrective date
Comment:	Refer to FIR #691200490 dated 9/25/2018 and/or Location # 306264 for additional equipment info.		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Other	#		

Comment:	Casing head. Observed audible hissing of gas underneath casing head in where casing is threaded into casing head. Dry vapor only. No fluid observed. Mechanical Conditions. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. Isolate or repair leak (24 hours).		
Corrective Action:	Isolate or repair leak (24 hours). Comply with Rule 605.d.	Date:	09/26/2018

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.484922,-104.460467
Comment:	Refer to FIR #691200490 dated 9/25/2018 and/or Location # 306264 for Tanks & Berms info.				
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				
				Date:

**Venting:**

Yes/No	NO		
Comment:			
Corrective Action:			
			Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	
	Date:

**Inspected Facilities**

Facility ID: 287412 Type: WELL API Number: 123-24320 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: PRODUCTION RECORDS

Comment: SI. COGCC records indicate SI since 04/2016.  
Mechanical Integrity Testing (Shut-in Wells)  
No current MIT on record or delinquent as required by Rule 326 (10 days).

Corrective Action: No current MIT on record or delinquent as required by Rule 326.  
Comply with Rule 326.b.  
Contact dnr\_cogccengineering@state.co.us with resolution plan.

Date: 10/05/2018

**BradenHead**

Comment: Bradenhead appears plumbed to surface.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
691200493	site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4588845">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4588845</a>
691200494	Casing leak video	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4588846">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4588846</a>