

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2018

Submitted Date:

09/19/2018

Document Number:

691200466**FIELD INSPECTION FORM**Loc ID 330359 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments3 Number of Corrective Actions

- ☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
		dnr_cogccengineering@state.co.us	
Pesicka, Conor		conor.pesicka@state.co.us	
,		regulatory@foundationenergy.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251165	WELL	SI	06/01/2016	WA	123-18968	SOONER 21-16-9	SI

General Comment:

This is a WELL Inspection. Refer to FIR #691200458 dated 9/18/2018 and/or Location #327361 for Battery info.
 This is a follow up inspection to FIR #684903893 dated 7/7/2017 & FIR #682503860 dated 9/5/2018.
 Any corrective action(s) from previous inspections that have not been addressed are still applicable.

Location				
Lease Road:				
Type	Access			
comment:				
Corrective Action	L			Date:
Overall Good: <input checked="" type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:				
Corrective Action:				Date:
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	PUMP JACK			
Comment:	Iron mesh panel			
Corrective Action:				Date:
Equipment:				
Type:		#		corrective date
Comment:	Refer to FIR #691200458 dated 9/18/2018 and/or Location ID #327361 for additional equipment info.			
Corrective Action:				Date:
Type: Deadman # & Marked		# 4		
Comment:	4/4-marked			
Corrective Action:				Date:
Type: Pump Jack		# 1		
Comment:	Mechanical Conditions. (30 Days).			
Corrective Action:	Remove or remediate stained soil around wellsite and pump jack area. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d. CA date from previous FIR #684903893 dated 7/7/2017 remains applicable.			Date: 08/15/2016
Type: Prime Mover		# 1		
Comment:	Electric motor			
Corrective Action:				Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
			CENTRALIZED BATTERY		40.652220,-103.869760	
Comment:	Refer to FIR #691200458 dated 9/18/2018 and/or Location ID #327361 for Tanks & Berms info.					
Corrective Action:					Date:	

Paint

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 251165 Type: WELL API Number: 123-18968 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: Observed well SI. Production records indicate SI since 6/2016.
Mechanical Integrity Testing (Shut-in Wells)
No current MIT on record or delinquent as required by Rule 326 (10 Days).

Corrective Action: CA from FIR #682503860 dated 9/5/2018 remains applicable.
Comply with Rule 326.b .
Contact dnr_cogccengineering@state.co.us with resolution plan.

Date: 09/20/2018**BradenHead**

Comment: Bradenhead does NOT appear plumbed to surface.

Corrective Action: Plumb bradenhead to surface.
Mechanical conditions (30 Days).
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.
Previous CA date from FIR #684903893 dated 7/7/2017 remains applicable.

Date: 08/07/2017

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401768187	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4583259
691200467	Site photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4583252