

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/18/2018

Submitted Date:

09/19/2018

Document Number:

691200468**FIELD INSPECTION FORM**
 Loc ID 330509 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_
**Operator Information:**OGCC Operator Number: 10112Name of Operator: FOUNDATION ENERGY MANAGEMENT LLCAddress: 5057 KELLER SPRINGS RD STE 650City: ADDISON State: TX Zip: 75001**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**12 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
,		regulatory@foundationenergy.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
251423	WELL	SI	06/01/2014	GW	123-19226	SOONER UNIT 21-6-15	SI

**General Comment:**

This is a WELL Inspection. Refer to FIR #691200458 dated 9/18/2018 and/or Location #327361 for Battery info.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	WELLHEAD			
Comment:				
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:				
Corrective Action:				Date: _____
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	Unused equipment near pump jack. See photos. Statewide unused equipment requirements (30 Days). Refer to Rule 603.f for guidance.			
Corrective Action:	Remove unused equipment. Comply with Rule 603.f .		Date:	10/19/2018
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	PUMP JACK			
Comment:	Iron mesh panel			
Corrective Action:			Date:	
Type	WELLHEAD			
Comment:	Barbed wire			
Corrective Action:			Date:	
<b>Equipment:</b>				
Type: Prime Mover	# 1		corrective date	
Comment:	Electric motor			
Corrective Action:			Date:	
Type: Pump Jack	# 1			
Comment:	Mechanical Conditions. (30 Days).			
Corrective Action:	Remove or remediate stained soil around wellsite and pump jack area. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date:	10/19/2018

Type:	#	
Comment:	Refer to FIR #691200458 dated 9/18/2018 and/or Location ID #327361 for additional equipment info.	
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment:	4/4-marked	
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
			CENTRALIZED BATTERY		40.652220,-103.869760
Comment:	Refer to FIR #691200458 dated 9/18/2018 and/or Location ID #327361 for Tanks & Berms info.				
Corrective Action:				Date:	

**Paint**

Condition	
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**Facility ID: 251423 Type: WELL API Number: 123-19226 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: PRODUCTION RECORDS

Comment: Observed well SI. Production records indicate SI since 6/2014.  
Last MIT: 11/3/2015.  
Next MIT Due: 11/3/2020.

Corrective Action: Date: **BradenHead**

Comment: Bradenhead does NOT appear plumbed to surface.

Corrective Action: Plumb bradenhead to surface.  
Mechanical conditions (30 Days).  
Securely fasten all valves, pipes, and fittings to ensure good mechanical condition,  
inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 10/19/2018

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401768188	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4583260">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4583260</a>
691200469	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4583253">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4583253</a>