

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #1 – Facility sign.



Photo #2 – Pig station located at entrance to pad.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #3 – Overview of meter sheds and chemical storage containers lining south side of pad, view from SW corner.



Photo #4 – Additional chemical storage containers at SE corner of pad.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #5 – Frac tank located at NE corner of pad.



Photo #6 - View of wellheads from SE corner of pad.



Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #7 – Localized accumulation of oil-stained soil at WF 04B-27 K22 596 wellhead.



Photo #8 – Sign affixed to wellhead from previous photo.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #9 - Localized accumulation of oil-stained soil at K22 04A-27 WF04A-27 K22 596 wellhead.



Photo #10 - Sign affixed to wellhead from previous photo.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #11 - Localized accumulation of oil-stained soil at wellhead. Note that this wellhead did not have a sign attached.



Photo #12 – The well in previous photo was located immediately south of K22 16A-27 WF16A-21 K22 596 wellhead.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #13 – Localized accumulations of oil-stained soil in two areas located SW of wellheads.



Photo #14 – 250 bbl produced water AST with lined, metal berm.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #15 – 2” and 1” PVC risers located in center of pad appear to be temporary monitoring wells.



Photo #16 – View of soil stockpiles and open flowline excavation from NE. There was no visible liner beneath either soil stockpile on date of inspection.

Inspection Photos

Location Name: N. Parachute WF K22 596 Pad

Location ID: #335648

Inspection Date: September 21, 2018



Photo #17 – Looking into open flowline excavation from north side. Note 2" flowlines and black electrical conduit inside of excavation.



Photo #18 – View of flowlines from east side of excavation.