

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/25/2018

Submitted Date:

09/25/2018

Document Number:

689801662**FIELD INSPECTION FORM**Loc ID 313291 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 95960Name of Operator: WEXPRO COMPANYAddress: P O BOX 45003City: SALT LAKE CITY State: UT Zip: 84145-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Fredrickson, Tammy	307-352-7566	Tammy.Fredrickson@questar.com	
		dnr_cogccengineering@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
284833	WELL	SI	05/01/2018	GW	081-07307	HIAWATHA DEEP UNIT 8 R	WK

General Comment:

Routine FIU inspection - MIT witness.

Inspected FacilitiesFacility ID: 284833 Type: WELL API Number: 081-07307 Status: SI Insp. Status: WK**Workover**

Comment: Inspector on location to witness MIT. Form 42 10 day notice document number 401764742.
 Test witnessed but NOT passed in field due to fact that packer was 147 feet from top of perms.

Corrective Action: Contact dnr_cogccengineering@state.co.us with resolution plan.Date: 10/05/2018**COGCC Comments**

Comment	User	Date
Inspector on location to witness MIT. Form 42 10 day notice document number 401764742. Test witnessed but NOT passed in field due to fact that packer was 147 feet from top of perms.	waldrone	09/25/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801669	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4589701