

Well Name : Navajo Lake 32-5 21-2

API # : 007-06308



Photo 1: Wellhead sign.



Photo 2: Location overview.

Well Name : Navajo Lake 32-5 21-2
API # : 007-06308



Photo 3: Trash and debris in corner of location.



Photo 4: Dried Kochia debris along W perimeter fencing.

Well Name : Navajo Lake 32-5 21-2

API # : 007-06308



Photo 5: Waddle netting and wire debris outside fencing in E perimeter.



Photo 6: Dried Kochia debris at top of cut slope.

Well Name : Navajo Lake 32-5 21-2

API # : 007-06308



Photo 7: Sediment flow onto location from NE corner cobble run and erosion channel outside cobble.



Photo 8: Sediment plume on location.

Well Name : Navajo Lake 32-5 21-2

API # : 007-06308



Photo 9: Rilling and erosion on S fill slope.



Photo 10: Rilling and erosion on S fill slope.

Well Name : Navajo Lake 32-5 21-2
API # : 007-06308



Photo 11: Erosion channel on S fill slope.



Photo 12: Erosion channel on S fill slope.