

Inspector Name:

FORM
INSP

Rev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2018

Submitted Date:

09/28/2018

Document Number:

688800289

FIELD INSPECTION FORM

Loc ID 325168 Inspector Name: On-Site Inspection ☐ 2A Doc Num:

Operator Information:

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

9 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214188	WELL	PR	01/01/1995	GW	067-05508	IGNACIO 33-8 2	EI

General Comment:

On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Ignacio 33-8 #2. For the most recent field inspection report of this facility, please refer to document #680602725. Corrective action required by that document had been completed by the time of this inspection.

Inspector Name:

Location				
<u>Lease Road:</u>				
Type	Access			
comment:				
Corrective Action	L		Date:	
Overall Good: <input checked="" type="checkbox"/>				
<u>Signs/Marker:</u>				
Type	WELLHEAD			
Comment:	Sign mounted to meter shack.			
Corrective Action:			Date:	
Emergency Contact Number:				
Comment:	Posted on location sign.			
Corrective Action:				Date: _____
<u>Good Housekeeping:</u>				
Type	DEBRIS			
Comment:	Corrective action from inspection document #680602725 has been completed.			
Corrective Action:			Date:	
Overall Good: <input checked="" type="checkbox"/>				
<u>Spills:</u>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<u>Equipment:</u>				corrective date
Type: Gas Meter Run	# 1			
Comment:				
Corrective Action:				Date:
Type: Gathering Line	# 1			
Comment:	Williams Field Services gathering line riser near SW corner of location.			
Corrective Action:				Date:
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Flow Line	# 1			
Comment:				
Corrective Action:				Date:
<u>Venting:</u>				
Yes/No				
Comment:				

Inspector Name:

Corrective Action:		Date:	
Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities									
Facility ID:	214188	Type:	WELL	API Number:	067-05508	Status:	PR	Insp. Status:	EI

Inspector Name: _____

Environmental

Spills/Releases:

Type of Spill: _____

Estimated Spill Volume: _____

Comment: _____

Corrective Action: _____

Date: _____

Reportable: _____

GPS: Lat _____

Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: 0310113

Owner Name: Adams

Lat _____ Long _____

GPS : 37.133327 -107.668836

Field Parameters:

Sample Location: _____

Comment: _____

Inspector Name:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment:

Corrective Action:

Date: _____

Pits: ☒ NO SURFACE INDICATION OF PITType: Evaporation

Lined:

Pit ID: 105402Lat: 37.131319Long: -107.670632

Reference Point: _____

Other: _____

Length: _____

Width: _____

Lining:

Liner Type:

Liner Condition:

Comment:

Historical Pit.

Corrective Action

Contact COGCC EPS staff for directives per Rule 905.b.

Date:

10/08/2018**Fencing:**

Fencing Type:

Fencing Condition:

Comment:

Corrective Action

Date:

Netting:

Netting Type:

Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present:

Oil Accumulation:

2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the Logos Operating LLC Ignacio 33-8 #2. For the most recent field inspection report of this facility, please refer to document #680602725. Corrective action required by that document had been completed by the time of this inspection. Pit Facility ID #105402 is listed in the COGIS database as a 10' by 10' by 6' evaporation pit with an unknown status. Per Rule 905.b contact SW EPS for directives. No surface indication of pit was observed during this field inspection.	hughesj	09/28/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/webblink/>) and search by document number:

Document Num	Description	URL
688800290	Inspection Photos	http://ogccwebblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4592614