

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/12/2018

Submitted Date:

09/28/2018

Document Number:

688800299

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
326341 _____ Hughes, Jim _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10000
Name of Operator: BP AMERICA PRODUCTION COMPANY
Address: 380 AIRPORT RD
City: DURANGO State: CO Zip: 81303

Findings:

- 13 Number of Comments
1 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

| Contact Name | Phone | Email | Comment |
|------------------|--------------|--------------------------|---------------------------------------|
| Fischer, Alex | | alex.fischer@state.co.us | |
| Beebe, Sabre | 970-779-9398 | Sabre.Beebe@bpx.com | SW Inspection Reports |
| Inspections, All | | SanJuanCOGCC@bp.com | SW Inspection Reports |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------------------|-------------|
| 216264 | WELL | PR | 12/01/2017 | GW | 067-07870 | BONIFACIO GALLEGOS A 1 | EI |

General Comment:

On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Bonifacio Gallegos A #1. For the most recent field inspection report of this facility, please refer to document #670602738.

| Location | | | |
|--|--|--------|------------------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | | | |
| Corrective Action | | | Date: |
| Overall Good: <input checked="" type="checkbox"/> | | | |
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Free standing sign near location entrance. | | |
| Corrective Action: | | | Date: |
| Emergency Contact Number: | | | |
| Comment: | Posted on location sign. | | |
| Corrective Action: | | | Date: _____ |
| Overall Good: <input type="checkbox"/> | | | |
| Spills: | | | |
| Type | Area | Volume | |
| In Containment: No | | | |
| Comment: | | | |
| <input type="checkbox"/> Multiple Spills and Releases? | | | |
| Fencing/: | | | |
| Type | PUMP JACK | | |
| Comment: | Chain link guard fencing around pump jack. | | |
| Corrective Action: | | | Date: |
| Type | WELLHEAD | | |
| Comment: | Stock panel enclosure around well head. | | |
| Corrective Action: | | | Date: |
| Type | SEPARATOR | | |
| Comment: | Stock panel fencing around all production equipment on site. | | |
| Corrective Action: | | | Date: |
| Equipment: | | | |
| Type: Ancillary equipment | # 1 | | corrective date |
| Comment: | Telemetry | | |
| Corrective Action: | | | Date: |
| Type: Pump Jack | # 1 | | |
| Comment: | Lube oil leaking from east side of pump jack. Absorbent rags are saturated with oil. Staining on concrete foundation and surrounding gravel. | | |
| Corrective Action: | Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. | | Date: 10/29/2018 |
| Type: Vertical Heated Separator | # 1 | | |
| Comment: | Combo separator/meter unit. | | |
| Corrective Action: | | | Date: |

| | | | |
|---------------------------|----------------|-------|--|
| Type: Ancillary equipment | # 1 | | |
| Comment: | Valve station. | | |
| Corrective Action: | | Date: | |
| Type: Bird Protectors | # 1 | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | | |
|--------------------|--|-------|--|
| Type | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Inspected Facilities

Facility ID: 216264 Type: WELL API Number: 067-07870 Status: PR Insp. Status: EI

Reclamation - Storm Water - Pit

Storm Water:

| | | | | | | |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
| Compaction | Pass | Compaction | Pass | | | |

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

| Comment | User | Date |
|---|----------|------------|
| <p>On September 12, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Bonifacio Gallegos A #1. For the most recent field inspection report of this facility, please refer to document #670602738.</p> <p>During this inspection a lube oil leak was observed on the east side of the pump jack. The concrete pad and the surrounding gravel are stained. Absorbent rags used to control the leak are saturated with oil.</p> | hughesjo | 09/28/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-------------------|---|
| 688800300 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4593468 |