

Inspection Photos

Location Name: West Fork 3-Phase Line Spill

Spill/Release ID: #457694

Inspection Date: October 1, 2018



Photo #1 – View into flowline excavation from north side. Arrow indicates pothole location.



Photo #2 – View of irrigation pond and straw wattle immediately south of excavation. No surface expressions of released fluids were observed in area between excavation and pond. There was no visible sheen or odor observed at pond on inspection date.

Inspection Photos

Location Name: West Fork 3-Phase Line Spill

Spill/Release ID: #457694

Inspection Date: October 1, 2018



Photo #3 – View into pothole located at southwest corner of excavation. Impacted soil and hydrocarbon odor were observed inside of pothole on inspection date.



Photo #4 – Excavated soil was being hauled to lined stockpile at nearby N. Parachute West Fork J25A 596 pad.

Inspection Photos

Location Name: West Fork 3-Phase Line Spill

Spill/Release ID: #457694

Inspection Date: October 1, 2018



Photo #5 – Soil stockpile at nearby pad. Note that operator was not segregating clean overburden from impacted soil on inspection date.



Photo #6 – COGCC inspectors walked a length of West Fork Parachute Creek on inspection date. Creek was dry with no visible impacts from subject release.