

Inspection Photos

Operator: BP America

API: 05-067-06778

Date: 9/25/2018



Photo 1. View of the eastern portion of the project area from the northeastern corner facing southward. Revegetation is grazed and largely comprised of grasses such as western wheatgrass (*Pascopyrum smithii*) and sand dropseed (*Sporobolus cryptandrus*).



Photo 2. View of the western project area from the southwestern edge facing northward.



Photo 3. View of cobble run-downs in the eastern project area facing eastward.



Photo 4. View of area along the eastern edge of the working area where scouring and erosional rilling is occurring.



Photo 5. View of erosion at culvert outlet in southeastern project area.



Photo 6. View of the southwestern corner of the project area where stormwater run-on is eroding the well pad cut-slope and depositing sediment down-slope.