

**Inspection Photos**  
**Location Name: Chavez #1**  
**API: 05-007-06120**



**Stained soil beneath truck load out valve on AST.**



**Weeds have been removed from location.**

**Inspection Photos**  
**Location Name: Chavez #1**  
**API: 05-007-06120**



**Extent of excavation on arrival.**



**Open excavation was dry at the time of this site visit.**

**Inspection Photos**  
**Location Name: Chavez #1**  
**API: 05-007-06120**



**Chavez water well with metal drum as cover.**



**Cover removed from Chavez water well.**