

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

09/19/2018

Submitted Date:

09/26/2018

Document Number:

685305361**FIELD INSPECTION FORM**Loc ID 325965 Inspector Name: St John, William (Cal) On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**23 Number of Comments5 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	<a href="#">SW Inspection Reports</a>
Inspections, All		SanJuanCOGCC@bp.com	<a href="#">SW Inspection Reports</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215643	WELL	PR	12/13/2000	GW	067-07248	LOBATO A 1	PR

**General Comment:**[Inspection completed as routine inspection requirement.](#)[This inspection does not alleviate requirement for operator to complete any open corrective actions from previous inspections.](#)[See link at end of report for path to downloadable pictures.](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action	L		Date:
Overall Good: <input type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Old wellhead sign at location.		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Operator contact information posted on wellhead sign.		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:	Weeds and grass growing inside fenced production equipment areas. Canadian thistle growing on location in graveled area and perimeter.		
Corrective Action:	Remove weeds and grass to comply with Rule 603.f.		Date: 10/27/2018
Type	UNUSED EQUIPMENT		
Comment:	Unused stock panel fencing on S perimeter of graveled area.		
Corrective Action:	Remove fence panels to comply with Rule 603.f.		Date: 10/27/2018
Type	DEBRIS		
Comment:	Concrete debris on location where anchor points were removed.		
Corrective Action:	Remove debris to comply with Rule 603.f.		Date: 10/27/2018
Overall Good: <input type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Stock panel fencing.		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Steel mesh safety barrier.		
Corrective Action:			Date:

Type	SEPARATOR		
Comment:	<a href="#">Stock panel fencing.</a>		
Corrective Action:		Date:	
Type	OTHER		
Comment:	<a href="#">Telemetry equipment - Stock panel fencing.</a>		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	<a href="#">Stock panel fencing.</a>		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Electrical control equipment.</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Electrical supply equipment.</a>		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Wellhead.</a>		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	<a href="#">Telemetry equipment.</a>		
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Flow Line	# 2		
Comment:	<a href="#">In use - 3" steel line from wellhead casing and tubing to separator inlet. All points co-located.</a> <a href="#">In use - 3" steel line from separator outlet to gas meter inlet. All points co-located.</a>		
Corrective Action:		Date:	
Type: Vertical Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	<a href="#">Electric motor.</a>		
Corrective Action:		Date:	
Type: Other	# 1		
Comment:	<a href="#">Water can and valve set.</a>		

Corrective Action:					Date:	
<b>Tanks and Berms:</b>						
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV STEEL		,	
Comment:						
Corrective Action:					Date:	
<b>Paint</b>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<b>Berms</b>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Insufficient	Base Insufficient	Inadequate		
Comment: Weeds and grass noted growing on berms and base areas of tank containment.						
Corrective Action: Repair or install berms or other secondary containment device to comply with Rule 605.a. (4).					Date: 10/27/2018	
<b>Venting:</b>						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
<b>Flaring:</b>						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	215643	Type:	WELL	API Number:	067-07248	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:		PR.							
Corrective Action:								Date:	

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Waddles	Fail					
Ditches	Pass	Gravel	Pass			
Compaction	Fail	Ditches	Pass			
Gravel	Pass					
Rip Rap	Pass					
Berms	Pass	Compaction	Pass			

Comment: Cut slope in NW corner of location has erosion channel. Erosion channel starts at to of slope and eroding slope face. Waddles in N and W perimeter. N waddle is under cut and not functioning. W waddle is full on backside and no longer functioning.

Corrective Action: Install or repair required BMPs to comply with Rule 1002.f.

Date: 10/27/2018

**Pits:** ☒ NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401775722	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590195">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590195</a>
685305449	Inspection photos.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590186">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4590186</a>