

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/27/2018

Submitted Date:

10/03/2018

Document Number:

685305464

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
313559 _____ St John, William (Cal) _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10343
Name of Operator: QEP ENERGY COMPANY
Address: 1050 17TH STREET - SUITE 800
City: DENVER State: CO Zip: 80265

Findings:

- 21 Number of Comments
4 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Pesicka, Conor		conor.pesicka@state.co.us	
Labowskie, Steve		steve.labowskie@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
Maez, Leonard	(970) 564-1699/ (806) 435-0529	leonard.maez@qepres.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
224474	WELL	SI	02/01/2017	OW	083-06539	ISLAND BUTTE UNIT II 6	SI

General Comment:

[Inspection completed as routine inspection requirement.](#)

[This inspection does not alleviate requirement for operator to complete any open corrective actions from previous inspections.](#)

[See link at end of report for path to downloadable pictures.](#)

Location			
Lease Road:			
	Type Access		
comment:			
Corrective ActionL		Date:	
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
	Type TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
	Type WELLHEAD		
Comment:			
Corrective Action:		Date:	
Emergency Contact Number:			
Comment:	<input type="text" value="Operator contact information posted on wellhead sign."/>		
Corrective Action:	<input type="text"/>		Date: _____
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Disconnected pipe section on SE corner of location.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	11/04/2018
Type	UNUSED EQUIPMENT		
Comment:	Steel building on W side of tanks used for pump or compressor building no longer has equipment installed and appears to not be in use.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	01/05/2019
Type	UNUSED EQUIPMENT		
Comment:	3 concrete slabs between tanks and heater treater. Equipment has been removed and slabs are not in use.		
Corrective Action:	Remove unused equipment to comply with Rule 603.f.	Date:	01/05/2019
Type	UNUSED EQUIPMENT		
Comment:	Identified (23) unused risers/flowlines. Flowline risers not LO/TO or marked are considered unused equipment. For unused, unmarked flowline risers 24 hrs to lock out tag out. 30 days to remove riser.		
Corrective Action:	Comply with Rule 603.f.	Date:	11/04/2018
Type	OTHER		
Comment:	Impacted soil around base of wellhead and tank load out. Less than a 5 gallon bucket clean up.		
Corrective Action:		Date:	
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No _____			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	OTHER		
Comment:	Riser in SE corner - Steel post and pole barrier.		
Corrective Action:			Date:
Type	OTHER		
Comment:	Concrete slabs - Steel post and pole barrier.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Steel post and pole barrier.		
Corrective Action:			Date:
Equipment:			corrective date
Type: Flow Line	# 18		
Comment:	Unused - 2" steel riser at wellhead. (B) point unknown. Riser has closed valve and bull plug installed. Unused - (5) 2" steel risers at heater treater. (B) point unknown. Risers are open ended. Unused - (2) 2" steel risers at heater treater. (B) point unknown. Bull plug installed. Unused - 1" steel riser at heater treater. (B) point unknown. Riser is open ended. Unused - (3) 1" steel risers at concrete slabs. (B) point unknown. Risers are open ended. Unused - 2" steel riser at concrete slab. (B) point unknown. Riser has valve (closed) but no plug. Unused - (4) 3" steel risers at concrete slab. (B) point unknown. Riser is open ended. Unused - 3" steel riser at concrete slab. (B) point is unknown. Riser has valve but no plug installed.		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 1		
Comment:	Steel building used as pump or compressor building. Equipment has been removed.		
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:			Date:
Type: Flow Line	# 1		
Comment:	In use - 2" steel line from wellhead casing. (B) point unknown.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead.		
Corrective Action:			Date:
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:			Date:
Type: Other	# 3		

Comment:	Concrete slabs. No equipment.	Date:	
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	Unused - (4) 4" steel risers inside tank battery. Riser has plug installed. Unused - 1/2" steel riser insude tank battery. (B) point unknown. Riser is open ended.	Date:	
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		
Comment:	One tank is disconnected and appears to not be in use.				Date:
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficent	Base Sufficent	
Comment:	If location is returned to production berms will require maintenance.			Date:
Corrective Action:				Date:

Venting:

Yes/No	NO	Date:	
Comment:		Date:	
Corrective Action:		Date:	

Flaring:

Type		Date:	
Comment:		Date:	
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 224474 Type: WELL API Number: 083-06539 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action:

Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			

Comment: [Stormwater BMPs appear to be properly installed and functioning at time of inspection.](#)

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
685305498	Inspection photos.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597227