

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

09/29/2018

Submitted Date:

09/29/2018

Document Number:

689302017

FIELD INSPECTION FORM

Loc ID 323914 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 96850
Name of Operator: TEP ROCKY MOUNTAIN LLC
Address: PO BOX 370
City: PARACHUTE State: CO Zip: 81635

Findings:

- 6 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Rocky, TEP		COGCCInspectionReports@terraep.com	All Inspections
Kellerby, Shaun		shaun.kellerby@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211201	WELL	PR	11/04/1996	GW	045-06960	SAVAGE RMV-35-28	PR

General Comment:

This is a follow up inspection from DOC#689301849
CA's as specified as required were not met per Inspection #689301849.

Location						
Lease Road:						
Type	Access					
comment:						
Corrective ActionL					Date:	
Overall Good: <input checked="" type="checkbox"/>						
Emergency Contact Number:						
Comment:	1-970-285-9377					
Corrective Action:					Date:	
Good Housekeeping:						
Type	WEEDS					
Comment:	Uncontrolle weeds around wellhead, see photo					
Corrective Action:	Comply with Rule 603.f .				Date:	09/10/2018
Overall Good: <input type="checkbox"/>						
Spills:						
Type	Area	Volume				
In Containment: No						
Comment:						
<input type="checkbox"/> Multiple Spills and Releases?						
Fencing/:						
Type	WELLHEAD					
Comment:	Hog panel fencing					
Corrective Action:					Date:	
Equipment:						
Type: Plunger Lift	# 1				corrective date	
Comment:						
Corrective Action:					Date:	
Type: Ancillary equipment	# 1					
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	NO					
Comment:						
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities

Facility ID: 211201 Type: WELL API Number: 045-06960 Status: PR Insp. Status: PR

Producing Well

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
				Material Handling And Spill Prevention		
		Gravel				
Berms						
		Compaction				
Seeding						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401778825	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4593535
689302018	Inspection photo 689302018	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4593531