

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/03/2018

Submitted Date:

10/03/2018

Document Number:

689302050

**FIELD INSPECTION FORM**

Loc ID 324140 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 96850  
Name of Operator: TEP ROCKY MOUNTAIN LLC  
Address: PO BOX 370  
City: PARACHUTE State: CO Zip: 81635

**Findings:**

- 11 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**Contact Information:**

| Contact Name | Phone | Email                              | Comment                         |
|--------------|-------|------------------------------------|---------------------------------|
| Rocky, TEP   |       | COGCCInspectionReports@terraep.com | <a href="#">All Inspections</a> |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name     | Insp Status |
|-------------|------|--------|-------------|------------|-----------|-------------------|-------------|
| 258999      | WELL | PR     | 07/10/2001  | GW         | 045-07680 | SAVAGE RMV 121-27 | PR          |

**General Comment:**

[Routine Field Inspection.](#)

**Location**

|                    |        |  |       |
|--------------------|--------|--|-------|
| <b>Lease Road:</b> |        |  |       |
| Type               | Access |  |       |
| comment:           |        |  |       |
| Corrective ActionL |        |  | Date: |

Overall Good:

|                           |                |       |
|---------------------------|----------------|-------|
| Emergency Contact Number: |                |       |
| Comment:                  | 1-970-285-9377 |       |
| Corrective Action:        |                | Date: |

|                           |   |                  |
|---------------------------|---|------------------|
| <b>Good Housekeeping:</b> |   |                  |
| Type                      | WEEDS   |                  |
| Comment:                  | uncontrolled weeds on location, see photo     |                  |
| Corrective Action:        | Comply with Rule 603.f .                      | Date: 10/15/2018 |
| Type                      | UNUSED EQUIPMENT                              |                  |
| Comment:                  | Unused equipment near tank battery, see photo |                  |
| Corrective Action:        | Comply with Rule 603.f .                      | Date: 11/03/2018 |

Overall Good:

|  |      |        |  |
|--|------|--------|--|
| <b>Spills:</b>   |      |        |  |
| Type   | Area | Volume |  |
| In Containment: No                                     |      |        |  |
| Comment:   |      |        |  |
| <input type="checkbox"/> Multiple Spills and Releases? |      |        |  |

|                    |                    |       |
|--------------------|--------------------|-------|
| <b>Fencing/:</b>   |                    |       |
| Type               | WELLHEAD           |       |
| Comment:           | hog panel fencing. |       |
| Corrective Action: |                    | Date: |
| Type               | TANK BATTERY       |       |
| Comment:           | hog panel fencing. |       |
| Corrective Action: |                    | Date: |
| Type               | SEPARATOR          |       |
| Comment:           | hog panel fencing. |       |
| Corrective Action: |                    | Date: |

|                       |     |  |                 |
|-----------------------|-----|--|-----------------|
| <b>Equipment:</b>     |     |  | corrective date |
| Type: Gas Meter Run   | # 1 |  |                 |
| Comment:              |     |  |                 |
| Corrective Action:    |     |  | Date:           |
| Type: Bird Protectors | # 1 |  |                 |
| Comment:              |     |  |                 |

|                                   |   |       |  |
|-----------------------------------|---|-------|--|
| Corrective Action:                |   | Date: |  |
| Type: Ancillary equipment         | # 3   |       |  |
| Comment:                          | 2 chemical units at wellhead<br>1 chemical unit at meter run. |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Deadman # & Marked          | # 3   |       |  |
| Comment:                          |   |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Plunger Lift                | # 1   |       |  |
| Comment:                          |   |       |  |
| Corrective Action:                |   | Date: |  |
| Type: Horizontal Heated Separator | # 1   |       |  |
| Comment:                          |   |       |  |
| Corrective Action:                |   | Date: |  |

**Tanks and Berms:**

| Contents           | #           | Capacity  | Type      | Tank ID | SE GPS |
|--------------------|-------------|-----------|-----------|---------|--------|
| PRODUCED WATER     | 1           | <100 BBLS | STEEL AST |         |        |
| Comment:           | 80 bbl tank |           |           |         |        |
| Corrective Action: |             |           |           |         | Date:  |

**Paint**

|                  |          |
|------------------|----------|
| Condition        | Adequate |
| Other (Content)  |          |
| Other (Capacity) |          |
| Other (Type)     |          |

**Berms**

| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |
|--------------------|----------|---------------------|---------------------|-------------|
| Metal              | Adequate | Walls Sufficent     | Base Sufficent      | Adequate    |
| Comment:           |          |                     |                     |             |
| Corrective Action: |          |                     |                     | Date:       |

**Venting:**

|                    |       |
|--------------------|-------|
| Yes/No             | NO    |
| Comment:           |       |
| Corrective Action: | Date: |

**Flaring:**

|                    |       |
|--------------------|-------|
| Type               |       |
| Comment:           |       |
| Corrective Action: | Date: |

**Inspected Facilities**

Facility ID: 258999 Type: WELL API Number: 045-07680 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

**Environmental**

**Spill/Remediation:**

Comment:

Corrective Action:  Date:

Emission Control Burner (ECB): NO

Comment:

Pilot:  Wildlife Protection Devices (fired vessels): YES

**Reclamation - Storm Water - Pit**

**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
|                  |                 | Compaction              |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
| Seeding          |                 |                         |                       |               |                          |         |

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                | URL   |
|--------------|----------------------------|---|
| 401783270    | INSPECTION SUBMITTED       | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597182">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597182</a> |
| 689302051    | Inspection photo 689302051 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597176">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4597176</a> |