

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2018

Submitted Date:

10/10/2018

Document Number:

688400376**FIELD INSPECTION FORM**

Loc ID 320157 Inspector Name: Silver, Randy On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 31257Name of Operator: FRITZLER RESOURCES INCAddress: P O BOX 114City: FORT MORGAN State: CO Zip: 80701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**8 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**Contact Information:**

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202853	WELL	PR	05/06/1983	OW	001-08258	WAILES 3	PR

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____

Good Housekeeping:			
Type	DEBRIS		
Comment:	Statewide unused equipment, weeds, waste, and trash requirements. Rags and tape around polish rod and packing. Remove and repair packing		
Corrective Action:	Comply with Rule 603.f .		Date: 11/12/2018
Type	UNUSED EQUIPMENT		
Comment:	Statewide unused equipment, weeds, waste, and trash requirements. Unused belt guard either install or remove from location.		
Corrective Action:	Comply with Rule 603.f .		Date: 11/12/2018

Overall Good: ☐

Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			

Fencing/:			
Type	WELLHEAD		
Comment:	Steel pipe		
Corrective Action:			Date:

Equipment:				corrective date
Type: Pump Jack	# 1			
Comment:				
Corrective Action:			Date:	
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:			Date:	
Type: Prime Mover	# 1			
Comment:	Gas motor			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities				
Facility ID: 202853	Type: WELL	API Number: 001-08258	Status: PR	Insp. Status: PR
Producing Well				
Comment:	PR			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
PU was not running at time of inspection fuel gas line to motor was closed	silverr	10/10/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400377	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604321