

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/04/2018

Submitted Date:

10/04/2018

Document Number:

688400352

FIELD INSPECTION FORM

Loc ID 320225 Inspector Name: Silver, Randy On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 31257
Name of Operator: FRITZLER RESOURCES INC
Address: P O BOX 114
City: FORT MORGAN State: CO Zip: 80701

Findings:

- 13 Number of Comments
- 9 Number of Corrective Actions
- Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
Fritzler, Gene	(970) 867-9388	gfritzler@bresnan.net	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
203117	WELL	SI	02/01/2016	GW	001-08525	LINNEBUR 24-1	SI

General Comment:

Location			
Lease Road:			
Type	Access		
comment:	ROAD INTO LOCATION NEEDS TO BE REBUILT		
Corrective Action:	Location is within a designated setback location, maintain and repair access roads per Rule 604.c.(2)S.	Date:	10/06/2017
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	11/01/2018
Type	TANK LABELS/PLACARDS		
Comment:	NO PLACARDING ON PROD TANK		
Corrective Action:	Install sign to comply with Rule 210.d.	Date:	10/06/2017
Emergency Contact Number:			
Comment:	<input type="text"/>		
Corrective Action:	<input type="text"/>		Date: <input type="text"/>
Good Housekeeping:			
Type	UNUSED EQUIPMENT		
Comment:	Unused 2" pipe by well head and pid		
Corrective Action:	Comply with Rule 603.f .	Date:	11/01/2018
Type	OTHER		
Comment:	No cap on load line of production tanks		
Corrective Action:	Location is within a designated setback location, bullplug or cap all loadlines per Rule 604.c.(2)O.	Date:	10/11/2018
Type	WEEDS		
Comment:	CONTROL WEEDS ON LOCATION AND ROAD WAY		
Corrective Action:	Comply with Rule 603.f .	Date:	10/18/2018
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	<input type="text"/>		
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PIT		
Comment:	FENCE NEEDS REPAIRED AROUND PIT		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	09/21/2017

Equipment:		corrective date
Type: Plunger Lift	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 1	
Comment:		
Corrective Action:		Date:
Type: Horizontal Heated Separator	# 1	
Comment:		
Corrective Action:		Date:
Type: Deadman # & Marked	# 4	
Comment: Steel pipe		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLs	STEEL AST		39.573054,-103.560986
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Insufficient	Base Insufficient	Inadequate
Comment:	Inadequate berms around tank(s)			
Corrective Action:	Location is within an exception zone, repair or install berms or other secondary containment devices per Rule 604.c.(3)B.			Date: 10/06/2017

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 203117 Type: WELL API Number: 001-08525 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Type: Produced Water Lined: NO Pit ID: Lat: Long:

Reference Point: _____ Other: _____ Length: _____ Width: _____

Lining:

Liner Type: Liner Condition:

Comment:

Corrective Action

Date:

Fencing:

Fencing Type: Other Fencing Condition: Inadequate

Comment: Barbwire. Fence around pit in disrepair.

Corrective Action

Location is within a designated setback location, install fencing per Rule 604.c.(2)M.

Date: 09/21/2017

Netting:

Netting Type: Netting Condition:

Comment:

Corrective Action

Date:

Anchor Trench Present: Oil Accumulation: 2+ feet Freeboard:

Comment:

Corrective Action

Date:

COGCC Comments

Comment	User	Date
<u>Acess road totally overgrown with growth could not tell it was a road. Fence around pit in disrepair. No berm around production tanks.</u>	silverr	10/04/2018
<u>This is a follow up inspection to DOC#685503722 corrective actions have not been addressed.</u>		

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401785230	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599125
688400353	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4599119