

Inspection Photos

Operator: Hilcorp Energy Co.

API: 05-067-08229

Date: 10/03/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is well established in this portion of the interim reclamation area and comprised of grasses such as smooth brome (*Bromus inermis*), sand dropseed (*Sporobolus airoides*), and ponderosa pine trees (*Pinus ponderosa*).



Photo 3. View of erosional channels up to 1.5 feet wide and deep in the southern project area, as well as sparse vegetative cover.



Photo 4. View of diversion in the southeastern project area where concentrated stormwater is diverted off of the southwestern corner of the project area and sediment deposition is occurring outside of the project area.