

Inspection Photos

Operator: Hilcorp Energy Co.

API: 05-067-07799

Date: 10/03/2018



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Vegetation is becoming established with grasses such as western wheatgrass (*Pascopyrum smithii*) and forbs such as hairy goldenaster (*Heterotheca villosa*).



Photo 2. View of the eastern project area from the southeastern corner facing northward.



Photo 3. View of area in the northwestern project area where stormwater flows off of the well pad, scouring the rocky upper portions, and depositing sediment down-slope.



Photo 4. View of Canada thistles (*Cirsium arvense*), some treated and some alive, in the western project area. Approximately 15 individuals observed.