

FORM
INSPRev
X/15

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/11/2018

Submitted Date:

10/11/2018

Document Number:

688400409

FIELD INSPECTION FORM

Loc ID _____ Inspector Name: _____ On-Site Inspection
319995 _____ Silver, Randy _____ 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 76859
 Name of Operator: SCHREIDER & COMPANY INC
 Address: 240 W JESSUP ST
 City: BRIGHTON State: CO Zip: 80601

Findings:

- 16 Number of Comments
8 Number of Corrective Actions
 Corrective Action Response Requested

Contact Information:

Contact Name	Phone	Email	Comment
Gomez, Jason		jason.gomez@state.co.us	
SCHNEIDE, JEFF R	970-867-9437	jeff@schneiderenergy.com	PRESIDENT

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
202172	WELL	PR	04/01/2017	OW	001-07577	ROBBINS 24-11A	PR

General Comment:

Location

Overall Good:

Signs/Marker:

Type	BATTERY		
Comment:	Adequate		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:	Sign not posted or information inaccurate at well(s) or battery No placard on Produced water tank		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>11/12/2018</u>
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. Tried to contact operator number was not a working number		
Corrective Action:	Install sign to comply with Rule 210.b.		Date: <u>09/18/2017</u>

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	OTHER		
Comment:	Flowlines or crude oil transfer lines not maintained to prevent failures or leakage. Integrity issues not corrected. Valves not locked and tagged out.		
Corrective Action:	Maintain active and inactive flowlines and crude oil transfer lines to meet rule 1102.i.		Date: <u>10/12/2018</u>
Type	TRASH		
Comment:	Trash next to Sep, debris and trash inside PU house, PU house wall caved in.		
Corrective Action:	Comply with Rule 603.f .		Date: <u>10/25/2018</u>
Type	WEEDS		
Comment:	Weeds on entire location around all surface equipment		
Corrective Action:	Comply with Rule 603.f .		Date: <u>10/25/2018</u>
Type	OTHER		
Comment:	Stained soil and leaking pipe on inlet pipe to crude oil tank		
Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff.		Date: <u>10/12/2018</u>
Type	OTHER		
Comment:	Stained soil around PU and Sep.		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e		Date: <u>11/12/2018</u>

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	PUMP JACK		
Comment:	Barb wire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Inadequate fencing or Fencing in disrepair		
Corrective Action:	Location is within a designated setback location, install fencing per Rule 604.c.(2)M.	Date:	09/01/2017

Equipment:

			corrective date
Type: Deadman # & Marked	# 4		
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 2		
Comment:	Bird netting in disrepair on produced water tank		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Gas powered motor		
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	400 BBLs	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:				Date:		
Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	200 BBLs	Open Top		,	
Comment:						
Corrective Action:				Date:		
<u>Paint</u>						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
<u>Berms</u>						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment: Shares containment with crude oil tanks						
Corrective Action:				Date:		
<u>Venting:</u>						
Yes/No	NO					
Comment:						
Corrective Action:				Date:		
<u>Flaring:</u>						
Type						
Comment:						
Corrective Action:				Date:		

Inspected Facilities

Facility ID: 202172 Type: WELL API Number: 001-07577 Status: PR Insp. Status: PR

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

COGCC Comments

Comment	User	Date
This is a follow up inspection to DOC #685503529 All corrective actions have not been address. Site is becoming over grown with weeds and cows are damaging Surface equipment	silverr	10/11/2018

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688400410	loc pic	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4606279