

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID #421066



Pit Facility ID #421066 location photo.



Gauge stick in pit #4 read approximately 9.5'.

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID #421066



Upper Pit (#4), Facility ID #418790. Fence and netting are in good condition.



Lower Pit (#3), Facility ID #418791. Fence and netting are in good condition.

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID #421066



Gauge stick in Pit #3 read approximately 9'. No hydrotest pit level indicator marks were observed during this inspection.



Poly water transfer pipe, being prepared for transport during last inspection, remains on site.

Inspection Photos
Location Name: McIntyre Flowback Pits #3 and #4
Facility ID #421066



Poly water transfer pipe stored on location near SW corner of location.



Area used by water trucks for water transfer operations. Ensure adequate spill prevention during transfers.