

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



0/15/18

Location Photo #1



0/15/18

Location Photo #2,

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



Location Photo #3, holes in secondary containment

Location Photo #4, holes in secondary containment

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



Location Photo #5, unused flow line riser

Location Photo #6, 4 unused flow line risers

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



Location Photo #7, stained rock by separator



Location Photo #8, Stained rock in battery containment.

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



Location Photo #9, Stained rock in battery containment.

Location Photo #10, Stained rock in battery containment.

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



Location Photo #11, Stained rock in battery containment.



Location Photo #12, , Stained rock in battery containment.

**Inspection Photo
GMU 22-6
API # 045-18326
Inspection # 689302124**



Location Photo #13, Stained rock in battery containment.