

Inspection Photos  
Location Name: Spicer 3-32H  
API: 05-057-06469



**Photo 1. Overview of location taken at entrance facing south.**

Inspection Photos  
Location Name: Spicer 3-32H  
API: 05-057-06469



**Photo 2. Stained soil at wellhead.**



**Photo 3. Unmarked guy line anchor.**