


COLORADO

historical → ERF



99999999

ION COMMISSION

ORT



<input checked="" type="checkbox"/> NOTICE OF UNSATISFACTORY INSPECTION		1120 Lincoln Street, Suite 801 Denver, CO 80203 (303)894-2100	
<input type="checkbox"/> NOTICE OF SATISFACTORY INSPECTION			
API No. 05- (121 - 07102)		LEASE NAME: #3 Rediers	
LOCATION: NESW 2 - 2N - 54W		OPERATOR: Sullivan ?? Kencillit	
DATE: 3-6-97		INSPECTOR: EBB	
Insp. Type: <input checked="" type="radio"/>	Insp. Status: PA	PA: Y <input checked="" type="radio"/> N	Pass/Fail: P <input checked="" type="radio"/> F Viol.: Y <input checked="" type="radio"/> N NOV: Y <input checked="" type="radio"/> N

INSPECTION ITEM

COMMENTS

INPUT

Well ID Signs (Rule 210, 604.c(4))	Larry & Ed onsite visit	
Pits (Reserve/Production) (Rule 902, 903, 904, 905)	Grooms Bagler	
Fences (Rule 603.b.7, 604.C.(3), 1002.A)	Landowner Gene Mitchell	
Tank Battery Equipment (Rule 603.b.3, 604)		
Fire Walls/Berms/Dikes (Rule 603.b.12, 604)		
General Housekeeping (Rule 603)	00064912	
Spills (Oil/Water) (Rule 907)		
Bradenhead (Rule 207.b)	2" x 20' pipe 400' west of site	
Drilling Well/Workover (Rule 317)	5 1/2" casing, pump-cement pump base.	
Surface Rehabilitation (Rule 1002, 1003, 1004, 1103)	West 300' is cement treater base old flowline connections, and	
Miscellaneous	washed out area where water was drained,	

CORRECTIVE ACTION REQUIRED: Re-enter and confirm plugs, plug,
cut off casing 4' high, remove cement, junk, contour,
reseed and straw eroded areas.
Date Corrective Action Required By: Date Remedied:

This report is a Notice of Inspection. The Commission requires that you correct any deficiencies shown on this report in a timely manner. Failure to comply may result in enforcement action by the Commission.

3-14-97 Discussed site with Gene Mitchell → Landowner

APR 11 6 1997