

GM 14-27
Api# 05-045-07713
Inspection # 689701913



GM 14-27
Api# 05-045-07713
Inspection # 689701913



Unmarked deadmen

GM 14-27
Api# 05-045-07713
Inspection # 689701913



Faded capacity

GM 14-27
Api# 05-045-07713
Inspection # 689701913



Erosion of slope and sediment build up north west of wells.

GM 14-27
Api# 05-045-07713
Inspection # 689701913



Erosion and damage of check east of wells.

GM 14-27
Api# 05-045-07713
Inspection # 689701913



Riling of slope and sediment build up in ditch.

GM 14-27
Api# 05-045-07713
Inspection # 689701913



Erosion of slope east of separators



Erosion of slope east of separators

GM 14-27
Api# 05-045-07713
Inspection # 689701913



Washing rills at tank battery.