

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/03/2018

Submitted Date:

10/11/2018

Document Number:

680603162**FIELD INSPECTION FORM**Loc ID 326301 Inspector Name: ROY, CATHERINE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10133Name of Operator: HILCORP ENERGY COMPANYAddress: P O BOX 61229City: HOUSTON State: TX Zip: 77208**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name | Phone | Email | Comment |
|-------------------|----------------|---------------------|------------------------------------|
| Ray, Mandy | (505) 599-4083 | mray@hilcorp.com | All Inspections |
| Shorty, Priscilla | | pshorty@hilcorp.com | All SW Inspections |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|--------------------|-------------|
| 216193 | WELL | PR | 04/12/2000 | GW | 067-07799 | HUBER-BURKETT 2-26 | RI |

General Comment:

[This is an interim reclamation and stormwater inspection. Any corrective actions not addressed from previous inspections are still applicable.](#)

| Inspected Facilities | | | | | | | | | |
|----------------------|--------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID: | 216193 | Type: | WELL | API Number: | 067-07799 | Status: | PR | Insp. Status: | RI |

| |
|--|
| |
|--|

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: Project area is surrounded by ponderosa pine forest and open grassland mosaic. Revegetation is progressing within the interim reclamation areas.**1002 SITE PREPARATION AND STABILIZATION**

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? _____

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? _____

Comment _____

Corrective Action _____

Date _____

| | |
|--|---|
| Date Final Reclamation Started: _____ | Date Final Reclamation Completed: _____ |
| Final Land Use: _____ | |
| Reminder: _____ | |
| Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div> | |
| Well plugged _____ | Pit mouse/rat holes, cellars backfilled _____ |
| Debris removed _____ | No disturbance /Location never built _____ |
| Access Roads _____ | Regraded _____ Contoured _____ Culverts removed _____ |
| Gravel removed _____ | |
| Location and associated production facilities reclaimed _____ | Locations, facilities, roads, recontoured _____ |
| Compaction alleviation _____ | Dust and erosion control _____ |
| Non cropland: Revegetated 80% _____ | Cropland: perennial forage _____ |
| Weeds present _____ | Subsidence _____ |
| 1004.d. FINAL VEGETATION TRANSECT | |
| TRANSECT RESULTS OF DISTURBED AREA% | _____ |
| TRANSECT RESULTS OF REFERENCE AREA% | _____ |
| TOTAL % OF DESIRABLE VEGETATION COVER | _____ |
| VEGETATIVE COVER | _____ |
| Comment: | <div style="border: 1px solid black; height: 20px; width: 100%;"></div> |
| Corrective Action: | <div style="border: 1px solid black; height: 20px; width: 100%;"></div> |
| | Date _____ |

| | | |
|---------------------------|--|--|
| Overall Final Reclamation | Well Release on Active Location <input type="checkbox"/> | Multi-Well Location <input type="checkbox"/> |
|---------------------------|--|--|

Storm Water:

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| | | | | | | |

Comment: Erosional scouring and sediment deposition is occurring in the northwestern project area.

Corrective Action: Stormwater controls are needed to stabilize erosion in the northwestern project area.

Date: 11/12/2018

Pits: ☒ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|----------------------|---|
| 401792509 | INSPECTION SUBMITTED | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4605195 |
| 680603163 | Inspection Photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4605193 |