

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/10/2018

Submitted Date:

10/10/2018

Document Number:

689701893**FIELD INSPECTION FORM**Loc ID 335186 Inspector Name: LONGWORTH, MIKE On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10433Name of Operator: LARAMIE ENERGY LLCAddress: 1401 SEVENTEENTH STREET #1400City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:9 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
COGCC, Laramie	970-248-0497	cogccnotifications@laramie-energy.com	All inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
275532	WELL	PR	10/23/2012	GW	045-10345	CASCADE CREEK 705-22-43	PR
283504	WELL	PR	05/02/2007	GW	045-11927	CASCADE CREEK 797-05-06DA	PR
283506	WELL	PR	09/10/2007	GW	045-11928	CASCADE CREEK 797-05-12D	PR
283581	WELL	PR	03/31/2008	GW	045-11960	CASCADE CREEK 797-05-14DA	PR
283583	WELL	PR	04/11/2007	GW	045-11961	CASCADE CREEK 797-05-06DB	PR

General Comment:[Routine General Field Inspection](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 970-248-0497

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Equipment:**

Type: Horizontal Heated Separator	# 5		corrective date
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 5		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	

Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficient		Base Sufficient	Adequate	
Comment:						
Corrective Action:						Date:
Contents	#	Capacity	Type	Tank ID	SE GPS	
METHANOL	1	<50 BBLS	STEEL AST		,	
Comment:						
Corrective Action:						Date:
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity) 500 gallons						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)		Permeability (Base)	Maintenance	
Metal				Base Insufficient	Inadequate	
Comment: Base of secondary containment is rusted out.						
Corrective Action: Repair or install berms or other secondary containment devices per Rule 906.d.(1).						Date: 11/12/2018
Venting:						
Yes/No						
Comment:						
Corrective Action:						Date:
Flaring:						
Type						
Comment:						
Corrective Action:						Date:

Inspected Facilities				
Facility ID:	275532	Type:	WELL	API Number: 045-10345 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	283504	Type:	WELL	API Number: 045-11927 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	283506	Type:	WELL	API Number: 045-11928 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	283581	Type:	WELL	API Number: 045-11960 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:
Facility ID:	283583	Type:	WELL	API Number: 045-11961 Status: PR Insp. Status: PR
Producing Well				
Comment:	Producing well			
Corrective Action:				Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Compaction	Pass					
Gravel	Pass					
		Ditches	Pass			
Berms	Pass					
		Compaction	Pass			
		Gravel	Pass			
		Culverts	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401791950	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604569
689701894	Inspection 689701893 photo log	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4604563