

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/10/2018

Submitted Date:

10/19/2018

Document Number:

690900038

FIELD INSPECTION FORM

Loc ID 449274 Inspector Name: FISCHER, ALEX On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10598
Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC
Address: 123 ROBERT S KERR AVE
City: OKLAHOMA CITY State: OK Zip: 73102

Findings:

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

| Contact Name | Phone | Email | Comment |
|----------------|-------|--|---------|
| Hewins, Grant | | ghewins@sandridgeenergy.com | |
| Church, Matt | | mchurch@sandridgeenergy.com | |
| Neidel, Kris | | kris.neidel@state.co.us | |
| Waldron, Emily | | emily.waldron@state.co.us | |
| Laird, Spence | | sandridgeenvironmental@sandridgeenergy.com | |

General Comment:

On October 10, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Rabbit Ears 06851 23 Location (Location ID: 449274) and API 057-06598. Weather was partially cloudy and temperatures about 29 degrees Fahrenheit with approximately 3-inches of snow on the ground

The following is a summary:

- Enclosed frac tank located adjacent to API 057-06598. Tank was placard, but not labeled.
- Load in/load out hose open ended resting on concrete barrier.
- Apparent hydrocarbon sheen noted on snow melt water in front of tank battery and load in/load out area.
- 3- 675 bbl PR water tanks.
- 5- 675 bbl Oil tanks.

Location

Overall Good:

Signs/Marker:

| | | | |
|--------------------|--|-------|------------|
| Type | TANK LABELS/PLACARDS | | |
| Comment: | • Enclosed frac tank located adjacent to API 057-06598. Tank was placard, but not labeled. | | |
| Corrective Action: | Comply with Rule 210.d. | Date: | 11/19/2018 |

Emergency Contact Number:

| | | | |
|--------------------|----------------------|--|----------------------------|
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

Overall Good:

Spills:

| Type | Area | Volume | | |
|------|------|--------|--|--|
| | | | | |

In Containment: No

Comment:

Multiple Spills and Releases?

Venting:

| | | | |
|--------------------|----------------------|--|----------------------------|
| Yes/No | | | |
| Comment: | <input type="text"/> | | |
| Corrective Action: | <input type="text"/> | | Date: <input type="text"/> |

Flaring:

| | | |
|--------------------|----------------------|----------------------------|
| Type | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

Environmental

Spills/Releases:

Type of Spill: PRODUCED WATER

Estimated Spill Volume: _____

Comment: Apparent hydrocarbon sheen noted on snow melt water in front of tank battery and load in/load out area.

Corrective Action: Train and educate staff and contract personnel on house keeping with zero spills, drips, beneath valves, fittings, unions, and load out area.

Date: 11/18/2018

Reportable: NO

GPS: Lat _____ Long _____

Proximity to Surface Water: _____

Depth to Ground Water: _____

Water Well Complaint:

DWR Receipt Num: _____ Owner Name: _____ GPS : _____ Lat _____ Long _____

Field Parameters:

Sample Location: _____ Comment: _____

COGCC Comments

| Comment | User | Date |
|--|----------|------------|
| <p>On October 10, 2018, COGCC Environmental Staff (Alex Fischer) conducted an environmental field inspection of SandRidge Exploration & Production LLC's (SandRidge) Rabbit Ears 06851 23 Location (Location ID: 449274) and API 057-06598. Weather was partially cloudy and temperatures about 29 degrees Fahrenheit with approximately 3-inches of snow on the ground</p> <p>The following is a summary:</p> <ul style="list-style-type: none"> • Enclosed frac tank located adjacent to API 057-06598. Tank was placard, but not labeled. • Load in/load out hose open ended resting on concrete barrier. • Apparent hydrocarbon sheen noted on snow melt water in front of tank battery and load in/load out area. • 3- 675 bbl PR water tanks. • 5- 675 bbl Oil tanks. <p>Corrective Actions (CAs):</p> <ul style="list-style-type: none"> • By November 19, 2018 – Signs and Markers Tanks and Containers Comply with Rule 210.d. <p>Train and educate staff and contract personnel on house keeping with zero spills, drips, beneath valves, fittings, unions, and load out area.</p> | fischera | 10/19/2018 |

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|--|---|
| 690900039 | 20181010 SandRidge Inspection Rabbit Ears Location ID 449274 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615611 |
| 690900040 | INSP Photo Rabbit Ears Location 449274 20181010 | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615612 |