

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/18/2018

Submitted Date:

10/19/2018

Document Number:

689801763**FIELD INSPECTION FORM**
 Loc ID 428535 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10524Name of Operator: GRMR OIL & GAS LLCAddress: P.O. BOX 6280City: BROOMFIELD State: CO Zip: 80021**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:15 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Neidel, Kris		kris.neidel@state.co.us	
Griffis, Mike	720-235-5071	mike.griffis@grmroilandgas.com	All GRMR inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
430264	WELL	PR	11/04/2016	OW	081-07753	Deal Gulch 2-16	PR
430885	WELL	PR	03/26/2015	OW	081-07766	Deal Gulch 6-16	PR
430886	WELL	PR	03/01/2015	OW	081-07767	Deal Gulch 8-16	SI
430887	WELL	PR	04/01/2017	OW	081-07768	Deal Gulch 4-16	SI

General Comment:

Routine FIU inspection.

LocationOverall Good: ☒

Signs/Marker:			
Type	WELLHEAD		
Comment:	Sign not posted or information inaccurate at well(s) or battery. No wellhead sign on 6-16 well.		
Corrective Action:	Install sign to comply with Rule 210.b.	Date:	12/19/2018
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: 1-800-801-0453

Corrective Action:

Date: _____

Overall Good: ☐

Spills:			
Type	Area	Volume	
PW/CO	WELLHEAD	<= 1 bbl	
Comment:	Stained soil at every wellhead. Full cellars at every wellhead with a cellar.		
Corrective Action:	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff. Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.		Date: 10/22/2018

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Equipment:			corrective date
Type: Horizontal Heater Treater	# 2		
Comment:	40.38824, -107.49899		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	40.38824, -107.49899		
Corrective Action:		Date:	
Type: Pump Jack	# 3		
Comment:	Stained soil at all pumpjacks' exhaust. Bucket with oily fluid stored at wellhead.		

Corrective Action:	Control and contain spills/releases and clean up per Rule 906.a. Contact COGCC EPS staff. E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.		Date:	10/22/2018
Type: Bird Protectors	#			
Comment:				
Corrective Action:			Date:	
Type: Other	# 1			
Comment:	Linear rod pump			
Corrective Action:			Date:	
Type: Emission Control Device	# 3			
Comment:	40.38824, -107.49899			
Corrective Action:			Date:	
Type: Deadman # & Marked	#			
Comment:				
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	400 BBLS	HEATED STEEL AST		40.388400,-107.498890
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Adequate
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	7	400 BBLS	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Inspector Name: Waldron, Emily

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate			Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected FacilitiesFacility ID: 430264 Type: WELL API Number: 081-07753 Status: PR Insp. Status: PR**Producing Well**Comment: Pumping. Stained soil, bucket.Corrective Action: Date: Facility ID: 430885 Type: WELL API Number: 081-07766 Status: PR Insp. Status: PR**Producing Well**Comment: Pumping. Stained soil full cellar. No wellhead sign.Corrective Action: Date: Facility ID: 430886 Type: WELL API Number: 081-07767 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: Stained soilCorrective Action: Date: Facility ID: 430887 Type: WELL API Number: 081-07768 Status: PR Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily AbandonedReminder: Comment: Stained soil full cellar.Corrective Action: Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Ditches	Pass			
Berms	Pass					
		Culverts	Pass			
Gravel	Pass					
Compaction	Pass					
		Compaction	Pass			
Sediment Traps	Pass					
		Gravel	Pass			
Ditches	Pass					
Culverts	Pass					

Comment: No apparent soil migration; erosion or soil movement.

Corrective Action:

Date: _____

Pits: ☐ NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689801778	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4615935