

Inspection Photos

Location Name: 05-103-08085 (TAIGA FED 14I-20-4-102)

Location ID: 315211

Inspection: 679701377



Location



Unused equipment on location



Inspection Photos

Location Name: 05-103-08085 (TAIGA FED 14I-20-4-102)

Location ID: 315211

Inspection: 679701377



130 strings of tubing on location



RTU on location



Inspection Photos

Location Name: 05-103-08085 (TAIGA FED 14I-20-4-102)

Location ID: 315211

Inspection: 679701377



3 deadman on location



Rebar on location

