

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2018

Submitted Date:

10/16/2018

Document Number:

689801747**FIELD INSPECTION FORM**
 Loc ID 312938 Inspector Name: Waldron, Emily On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10407Name of Operator: ANTLER ENERGY LLCAddress: PO BOX 104City: BAGGS State: WY Zip: 82321**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:3 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Evans, Clay		antlerenergy@yahoo.com	
Neidel, Kris		kris.neidel@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
222936	WELL	PR	12/01/2017	GW	081-06298	ROSS-GOVERNMENT-USA 43-7	SI

General Comment:

Routine FIU follow up inspection. Follow up to inspection from 1/2/2018 document number 689800729. All FIU corrective actions have been met. Pit and land farm mentioned in previous report remain outstanding Environmental concerns. Pit and landfarm have corrective actions and dates associated with them. 1 FIU CA and date for trash.

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type

TRASH

Comment:

Used absorbent pads scattered between wellhead and and pit and around pit.

Corrective Action:

Comply with Rule 603.f .

Date: 10/26/2018

Overall Good: ☐**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	222936	Type:	WELL	API Number:	081-06298	Status:	PR	Insp. Status:	SI
Idle Well									
Purpose: <input checked="" type="checkbox"/> Shut In <input type="checkbox"/> Temporarily Abandoned Reminder: _____									
Comment: _____									
Corrective Action: _____ Date: _____									

Environmental**Waste Management:**

Type	Management	Condition	GPS (Lat) (Long)		
Oily Soil	Piles	Inadequate	40.926150	-108.327850	
Comment					
Corrective Action	E&P Waste not properly stored, handled, transported, treated, recycled, or disposed per Rule 907. Contact COGCC EPS staff.				Date: 10/16/2018

Spill/Remediation:

Comment:				
Corrective Action:				

Emission Control Burner (ECB): _____

Comment: _____

Pilot: _____ Wildlife Protection Devices (fired vessels): _____

COGCC Comments

Comment	User	Date
Follow up to inspection from 1/2/2018 document number 689800729. All FIU corrective actions have been met. Pit and land farm mentioned in previous report remain outstanding Environmental concerns. Pit and landfarm have corrective actions and dates associated with them. 1 FIU CA and date for trash.	waldrone	10/16/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401798947	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4611645
689801753	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4611643