

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/19/2018

Submitted Date:

10/19/2018

Document Number:

689302138

FIELD INSPECTION FORM

Loc ID 334938 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Operator Information:
 OGCC Operator Number: 10456
 Name of Operator: CAERUS PICEANCE LLC
 Address: 1001 17TH STREET #1600
 City: DENVER State: CO Zip: 80202

Findings:
8 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Elsener,		COGCC.inspections@caerusoilandgas.com	all Piceance inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261411	WELL	PR	05/28/2004	GW	045-07954	SHIDELER 25-2A1 (B25W)	PR
261412	WELL	PR	05/28/2004	GW	045-07955	SHIDELER 25-2A(B25W)	PR
266198	WELL	PR	05/28/2004	GW	045-09129	SHIDELER 25-2C (B25W)	PR
267578	WELL	PR	04/26/2004	GW	045-09200	SHIDELER 25-7 (B25W)	PR
267583	WELL	PR	10/07/2003	GW	045-09203	SHIDELER 25-1 (B25W)	PR
267584	WELL	PR	05/28/2004	GW	045-09204	SHIDELER 25-2D (B25W)	PR

General Comment:
 This is a follow up inspection from [Doc#689301816](#). Required Corrective Action items noted in previous inspections have been satisfied.
 Equipment inventory has not changed on location.

Inspected Facilities									
Facility ID:	261411	Type:	WELL	API Number:	045-07954	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	261412	Type:	WELL	API Number:	045-07955	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	266198	Type:	WELL	API Number:	045-09129	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	267578	Type:	WELL	API Number:	045-09200	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	267583	Type:	WELL	API Number:	045-09203	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				
Facility ID:	267584	Type:	WELL	API Number:	045-09204	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:					Date:				

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms						
Ditches						
Seeding						
		Compaction				
		Gravel				

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302139	Inspection photo 689302139	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617681