

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2018

Submitted Date:

10/22/2018

Document Number:

689302142**FIELD INSPECTION FORM**

Loc ID 335040 Inspector Name: Holtz, Darin On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 10531Name of Operator: VANGUARD OPERATING LLCAddress: 5847 SAN FELIPE #3000City: HOUSTON State: TX Zip: 77057**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
☐ FOLLOW UP INSPECTION REQUIRED
☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:21 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Ghan, Scott	970-744-8128	sgghan@vnrenergy.com	SR. EH&S
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
299214	WELL	PR	03/27/2010	GW	045-17614	MILLER 33B-36-692	PR
299215	WELL	PR	03/27/2010	GW	045-17615	MILLER 33C-36-692	PR
299216	WELL	PR	04/13/2010	GW	045-17616	MILLER 44D-36-692	PR
299217	WELL	PR	04/13/2010	GW	045-17617	MILLER 43A-36-692	PR
299218	WELL	PR	04/28/2010	GW	045-17618	MILLER 43D-36-692	PR
299219	WELL	PR	04/28/2010	GW	045-17619	MILLER 43C-36-692	PR
299220	WELL	PR	04/28/2010	GW	045-17620	MILLER 33D-36-692	PR
299221	WELL	PR	04/26/2010	GW	045-17621	MILLER 42A-36-692	PR
299222	WELL	PR	03/27/2010	GW	045-17622	MILLER 43B-36-692	PR
299223	WELL	PR	04/26/2010	GW	045-17623	MILLER 32A-36-692	PR

General Comment:

This is a follow up inspection from Doc# 689301896. Required Corrective Action items noted in previous inspections have been satisfied.

Location**Lease Road:**

Type	Access		
comment:			
Corrective Action:		Date:	

Overall Good: ☒**Emergency Contact Number:**

Comment:	1-800-921-8252	
Corrective Action:		Date:

Good Housekeeping:

Type	DEBRIS		
Comment:			
Corrective Action:		Date:	
Type	TRASH		
Comment:			
Corrective Action:		Date:	
Type	WEEDS		
Comment:			
Corrective Action:		Date:	

Overall Good: ☒**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel gates		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Panel gates		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 10		corrective date
Comment:			
Corrective Action:		Date:	

Type: Bird Protectors	# 12		
Comment:			
Corrective Action:			Date:
Type: Ancillary equipment	# 2		
Comment:	Chemical unit at wellheads		
Corrective Action:			Date:
Type: Horizontal Heater Treater	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 11		
Comment:			
Corrective Action:			Date:
Type: Pig Station	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	OTHER	STEEL AST		,	
Comment:	625 BBL					
Corrective Action:						Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Comment:						
Corrective Action:					Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	5	OTHER	HEATED STEEL AST		,	
Comment:	625 BBL Centralized battery					

Corrective Action:					Date:	
Paint						
Condition	Adequate					
Other (Content)						
Other (Capacity)						
Other (Type)						
Berms						
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance		
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate		
Comment:						
Corrective Action:					Date:	
Venting:						
Yes/No	YES					
Comment:	Bradenhead valves open to vent.					
Corrective Action:					Date:	
Flaring:						
Type						
Comment:						
Corrective Action:					Date:	

Inspected Facilities									
Facility ID:	299214	Type:	WELL	API Number:	045-17614	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299215	Type:	WELL	API Number:	045-17615	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299216	Type:	WELL	API Number:	045-17616	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299217	Type:	WELL	API Number:	045-17617	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299218	Type:	WELL	API Number:	045-17618	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299219	Type:	WELL	API Number:	045-17619	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299220	Type:	WELL	API Number:	045-17620	Status:	PR	Insp. Status:	PR
Producing Well									
Comment:	Well Producing on plunger lift								
Corrective Action:						Date:			
Facility ID:	299221	Type:	WELL	API Number:	045-17621	Status:	PR	Insp. Status:	PR

<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	299222	Type:	WELL
API Number:	045-17622	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	
Facility ID:	299223	Type:	WELL
API Number:	045-17623	Status:	PR
Insp. Status:	PR		
<u>Producing Well</u>			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
		Gravel				
				Material Handling And Spill Prevention		
Seeding						
Ditches						

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302143	Inspection photo 689302143	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617683