

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2018

Submitted Date:

10/22/2018

Document Number:

689302146

FIELD INSPECTION FORM

Loc ID 335505 Inspector Name: Holtz, Darin On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 10531
Name of Operator: VANGUARD OPERATING LLC
Address: 5847 SAN FELIPE #3000
City: HOUSTON State: TX Zip: 77057

Findings:

20 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	Sr. Production Foreman
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	SR. EH&S

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
279431	WELL	PR	03/01/2011	GW	045-11032	JACKSON 44D-28-692	PR
279432	WELL	PR	03/01/2011	GW	045-11033	JACKSON 33C-28-692	PR
279433	WELL	PR	03/01/2011	GW	045-11034	JACKSON 43C-28-692	PR
280246	WELL	PR	02/18/2009	GW	045-11223	JACKSON 34D-28-692	PR
298301	WELL	PR	01/20/2010	GW	045-17117	JACKSON 44C-28-692	PR
298794	WELL	PR	01/13/2010	GW	045-17426	JACKSON 43A-28-692	PR
298795	WELL	PR	01/11/2010	GW	045-17427	JACKSON 33D-28-692	PR
298796	WELL	PR	11/11/2010	GW	045-17428	JACKSON 33A-28-692	PR
298797	WELL	PR	01/13/2010	GW	045-17429	JACKSON 34C-28-692	PR
298798	WELL	PR	01/13/2010	GW	045-17430	JACKSON 44A-28-692	PR

General Comment:

This is a follow up inspection from Doc#689301927 .
Battery containment has water in it from the seasonal percipitation, can not verfy that stained rock has been addressed.
Deadmen anchor markers has been corrected.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:

Good Housekeeping:			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:

Overall Good:

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:			
Type	WELLHEAD		
Comment:	Panel gates		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Panel gates		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fencing.		
Corrective Action:			Date:

Equipment:			corrective date
Type: Horizontal Heated Separator	# 10		
Comment:			
Corrective Action:			Date:

Type: Ancillary equipment	# 2		
Comment:	2 chemical units at wellheads		
Corrective Action:			Date:
Type: Bird Protectors	# 9		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 10		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 7		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	HEATED STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	3	500 BBLs	STEEL AST		,
Comment:	Centralized battery				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate	
Comment:					
Corrective Action:				Date:	

Venting:

Yes/No	YES		
Comment:	Bradenhead valves open to vent.		
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	<u>279431</u>	Type:	<u>WELL</u>	API Number:	<u>045-11032</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>279432</u>	Type:	<u>WELL</u>	API Number:	<u>045-11033</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>279433</u>	Type:	<u>WELL</u>	API Number:	<u>045-11034</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>280246</u>	Type:	<u>WELL</u>	API Number:	<u>045-11223</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>298301</u>	Type:	<u>WELL</u>	API Number:	<u>045-17117</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>298794</u>	Type:	<u>WELL</u>	API Number:	<u>045-17426</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>298795</u>	Type:	<u>WELL</u>	API Number:	<u>045-17427</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>
Producing Well									
Comment:	<u>Well Producing on plunger lift</u>								
Corrective Action:					Date:				
Facility ID:	<u>298796</u>	Type:	<u>WELL</u>	API Number:	<u>045-17428</u>	Status:	<u>PR</u>	Insp. Status:	<u>PR</u>

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 298797 Type: WELL API Number: 045-17429 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Facility ID: 298798 Type: WELL API Number: 045-17430 Status: PR Insp. Status: PR

Producing Well			
Comment:	Well Producing on plunger lift		
Corrective Action:		Date:	

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Rip Rap						
Retention Ponds						
				Material Handling And Spill Prevention		
		Compaction				
Culverts						
Ditches						
Berms						

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302147	Inspection photo 689302147	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617685