

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2018

Submitted Date:

10/22/2018

Document Number:

689302148

**FIELD INSPECTION FORM**

Loc ID 335346 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: VANGUARD OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

12 Number of Comments  
0 Number of Corrective Actions  
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	<a href="#">SR. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
258296	WELL	PR	09/01/2004	GW	045-07633	JACKSON 15-28	PR
259436	WELL	PR	09/01/2004	GW	045-07725	JACKSON 16-28	PR

**General Comment:**

This is a follow up inspection from [Doc#689301929](#). Required Corrective Action items noted in previous inspections have been satisfied.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Emergency Contact Number:			
Comment:	Well Producing on plunger lift		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel gates		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence		
Corrective Action:			Date:
Type	TANK BATTERY		
Comment:	Panel gates		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Panel gates		
Corrective Action:			Date:

<b>Equipment:</b>		corrective date
Type: Horizontal Heated Separator	# 2	
Comment:		
Corrective Action:		Date:
Type: Plunger Lift	# 2	
Comment:		
Corrective Action:		Date:
Type: Bird Protectors	# 6	
Comment:		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Gas Meter Run	# 2	
Comment:		
Corrective Action:		Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	200 BBLs	HEATED STEEL AST		
Comment:	Centralized battery				
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	YES
Comment:	Bradenheads open to vent
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 258296 Type: WELL API Number: 045-07633 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

Facility ID: 259436 Type: WELL API Number: 045-07725 Status: PR Insp. Status: PR

**Producing Well**

Comment: [Well Producing on plunger lift](#)

Corrective Action:

Date:

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Gravel				
Berms						
Rip Rap						
Compaction						
		Compaction				
		Culverts				
Seeding						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302149	Inspection photo 689302149	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617686">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617686</a>