

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/22/2018

Submitted Date:

10/22/2018

Document Number:

689302150

**FIELD INSPECTION FORM**

Loc ID 335078 Inspector Name: Holtz, Darin On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 10531  
Name of Operator: VANGUARD OPERATING LLC  
Address: 5847 SAN FELIPE #3000  
City: HOUSTON State: TX Zip: 77057

**Findings:**

- 15 Number of Comments
- 0 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Aaron, Axelson	230-0926	aaxelson@vnrenergy.com	<a href="#">Sr. Production Foreman</a>
Ghan, Scott	970-744-8128	sghan@vnrenergy.com	<a href="#">SR. EH&amp;S</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
211294	WELL	PR	09/12/1996	GW	045-07053	PORTER FEDERAL 14-28-6-92	PR
279923	WELL	PR	08/16/2006	GW	045-11108	SPECIALTY FEDERAL 24D-28-692	PR
279924	WELL	PR	08/17/2006	GW	045-11109	SPECIALTY FEDERAL 24C-28-692	PR
279925	WELL	PR	08/09/2006	GW	045-11110	SPECIALTY FEDERAL 23A-28-692	PR

**General Comment:**

This is a follow up inspection from [Doc# 689301931](#). Required Corrective Action items noted in previous inspections have been satisfied.

**Location**

<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:

Overall Good:

Emergency Contact Number:			
Comment:	1-800-921-8252		
Corrective Action:			Date:

<b>Good Housekeeping:</b>			
Type	DEBRIS		
Comment:			
Corrective Action:			Date:
Type	WEEDS		
Comment:			
Corrective Action:			Date:
Type	TRASH		
Comment:			
Corrective Action:			Date:

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	TANK BATTERY		
Comment:	Hog panel fence		
Corrective Action:			Date:
Type	IGNITOR/COMBUSTOR		
Comment:	Hog panel fence		
Corrective Action:			Date:
Type	SEPARATOR		
Comment:	Hog panel fence		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Hog panel fence		
Corrective Action:			Date:

<b>Equipment:</b>			corrective date
Type: Deadman # & Marked	# 1		
Comment:			
Corrective Action:			Date:
Type: Plunger Lift	# 4		
Comment:			
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 4		
Comment:			
Corrective Action:			Date:
Type: Bird Protectors	# 11		
Comment:			
Corrective Action:			Date:
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:			Date:
Type: Emission Control Device	# 1		
Comment:			
Corrective Action:			Date:

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	1	200 BBLs	HEATED STEEL AST		,	
Comment:						
Corrective Action:						Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CONDENSATE	3	300 BBLs	HEATED STEEL AST		,	
Comment:	Centralized battery					
Corrective Action:						Date:

**Paint**

Condition	Adequate	
-----------	----------	--

Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
CONDENSATE	4	400 BBLs	HEATED STEEL AST		,

Comment:	Centralized battery
Corrective Action:	Date:

**Paint**

Condition	Adequate
-----------	----------

Other (Content)	Methanol tank
Other (Capacity)	500 gallon
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficent	Base Sufficent	Adequate

Comment:	
Corrective Action:	Date:

**Venting:**

Yes/No	YES
Comment:	Braden head valves open to vent.
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities			
Facility ID: <u>211294</u>	Type: <u>WELL</u>	API Number: <u>045-07053</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>279923</u>	Type: <u>WELL</u>	API Number: <u>045-11108</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>279924</u>	Type: <u>WELL</u>	API Number: <u>045-11109</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift</u>		
Corrective Action:		Date:	
Facility ID: <u>279925</u>	Type: <u>WELL</u>	API Number: <u>045-11110</u>	Status: <u>PR</u> Insp. Status: <u>PR</u>
<b>Producing Well</b>			
Comment:	<u>Well Producing on plunger lift</u>		
Corrective Action:		Date:	

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Compaction				
Berms						
		Gravel				
Ditches						
Seeding						

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
689302151	Inspection photo 689302151	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617687">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4617687</a>