

State of Colorado
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:
401763129

Date Received:
10/24/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

5 of 5 CAs from the FIR responded to on this Form

5 CA Completed
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Contact Name and Telephone:

Name: _____

Phone: () _____ Fax: () _____

Email: _____

Additional Operator Contact:

Contact Name

Phone

Email

Susana Lara-Mesa

303-825-4822

slaramesa@kpk.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 691401004

Inspection Date: 09/11/2018

FIR Submit Date: 09/11/2018

FIR Status: _____

Inspected Operator Information:

Company Name: KP KAUFFMAN COMPANY INC

Company Number: 46290

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

LOCATION - Location ID: 318202

Location Name: TOM L. RUSSELL UNIT E-62N67W Number: 30SWNE County: WELD

Qtrqtr: SWNE Sec: 30 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.111655 Longitude: -104.930411

FACILITY - API Number: 05-123-00 Facility ID: 240864

Facility Name: TOM L. RUSSELL UNIT E Number: 1

Qtrqtr: SWNE Sec: 30 Twp: 2N Range: 67W Meridian: 6

Latitude: 40.111655 Longitude: -104.930411

CORRECTIVE ACTIONS:

1 CA# 118592

Corrective Action: Repair leak or remove east crude oil tank. Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition per Rule 605.d.

Date: 12/11/2018

Response: CA COMPLETED

Date of Completion: 10/03/2018

Operator
Comment:

Stained soil on west side of east crude oil tank has been removed. Please see attached picture.

COGCC Decision: _____

COGCC
Representative:

2 CA# 118593

Corrective Action: Comply with Rule 603.f .

Date: 10/11/2018

Response: CA COMPLETED

Date of Completion: 10/03/2018

Operator
Comment:

Stained soil underneath valve in manifold located west of crude oil tanks has been removed. Please see attached pictures.

COGCC Decision: _____

COGCC
Representative:

3 CA# 118594

Corrective Action: Comply with Rule 603.f .

Date: 10/11/2018

Response: CA COMPLETED

Date of Completion: 10/03/2018

Operator
Comment:

Stained soil under north heated separator has been removed. Please see attached picture.

COGCC Decision: _____

COGCC
Representative:

4 CA# 118595

Corrective Action: Comply with Rule 603.f .

Date: 12/11/2018

Response: CA COMPLETED

Date of Completion: 09/18/2018

Operator
Comment:

The unused meter run inside the fenced in area is not KPK meter run. It belonged to Anadarko and is currently being used by them to hang their wireless production systems. That equipment has been tagged with a "Not Operated by KPK".

COGCC Decision: _____

COGCC
Representative:

5 CA# 118596

Corrective Action: Comply with Rule 603.f .

Date: 01/12/2018

Response: CA COMPLETED

Date of Completion: 09/13/2018

Operator
Comment:

Unused unmarked riser located North of East crude oil tank battery has been removed.

COGCC Decision: _____

COGCC
Representative:

OPERATOR COMMENT AND SUBMITTAL

Comment:

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Susana Lara-Mesa

Signed:

Title: VP of Engineering

Date: 10/24/2018 5:09:38 PM

ATTACHMENT LIST

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<u>Document Number</u>	<u>Description</u>
401802525	Removed stained soil PIC1
401802526	Removed stained soil PIC2
401802528	Removed stained soil PIC3
401802531	Removed stained soil PIC4

Total Attach: 4 Files