

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/16/2018

Submitted Date:

10/25/2018

Document Number:

688800327**FIELD INSPECTION FORM**
 Loc ID 419311 Inspector Name: Hughes, Jim On-Site Inspection ☐ 2A Doc Num:
Operator Information:OGCC Operator Number: 10000Name of Operator: BP AMERICA PRODUCTION COMPANYAddress: 380 AIRPORT RDCity: DURANGO State: CO Zip: 81303**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:10 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Baca, Matthew		matthew.baca@bpx.com	SW Inspection Reports
Inspections, All		SanJuanCOGCC@bp.com	SW Inspection Reports
Fischer, Alex		alex.fischer@state.co.us	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
419311	LOCATION	AC			-	PERINO WATER TRANSFER	EI
445606	SPILL OR RELEASE	CL	04/25/2016		-	SPILL/RELEASE POINT	EI

General Comment:

On October 16, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Perino Water Transfer Station Spill/Release Point #445606. Remediation Project #9673 was closed once analytical results were compliant with Table 910-1 standards.

Location

Lease Road:			
Type	Access		
comment:			
Corrective Action	L	Date:	

Overall Good: ☒

Signs/Marker:			
Type	OTHER		
Comment:	Free standing sign near access road intersection with county road. Information is incomplete on location sign for a tank battery.		
Corrective Action:	Install sign to comply with Rule 210.b	Date:	12/25/2018

Emergency Contact Number:

Comment: Posted on location sign.

Corrective Action: _____ Date: _____

Overall Good: ☒

Spills:				
Type	Area	Volume		

In Containment: No

Comment: _____

☐ Multiple Spills and Releases?

Fencing/:			
Type	OTHER		
Comment:	Transfer pump shack is enclosed with stock panels.		
Corrective Action:		Date:	

Equipment:			corrective date
Type: Other	# 1		
Comment:	Pump shack		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Telemetry equipment		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	2	400 BBLS	HEATED STEEL AST		37.015001,-107.449429
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		

Other (Type)

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Concrete	Adequate	Walls Sufficent	Base Sufficent	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities									
Facility ID:	419311	Type:	LOCATION	API Number:	-	Status:	AC	Insp. Status:	EI
Facility ID:	445606	Type:	SPILL OR	API Number:	-	Status:	CL	Insp. Status:	EI

Environmental	
Spill/Remediation:	
Comment:	Remediation Project #9673 was closed once soil sample results indicated compliance with Table 910-1 clean up standards.
Corrective Action:	<div></div> <div>Date: _____</div>
Emission Control Burner (ECB): _____	
Comment:	<div></div>
Pilot: _____	Wildlife Protection Devices (fired vessels): _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
		Culverts	Pass			
Compaction	Pass	Compaction	Pass			
		Gravel	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
On October 16, 2018 COGCC SW EPS Jim Hughes conducted an environmental field inspection of the BP Perino Water Transfer Station Spill/Release Point #445606. Remediation Project #9673 was closed once analytical results were compliant with Table 910-1 standards. Vegetation is sparse in the surrounding area due to cattle grazing. The remediated area appears to have similar vegetative cover as the land outside of the project area.	hughesjo	10/25/2018

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688800328	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4621817