

State of Colorado  
Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Document Number:  
401820207

Date Received:  
11/01/2018

FIR RESOLUTION FORM

Overall Status: CAC

CA Summary:

1 of 1 CAs from the FIR responded to on this Form

1 CA Completed  
0 Factual Review Request

OPERATOR INFORMATION

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

Contact Name and Telephone:

Name: \_\_\_\_\_

Phone: ( ) \_\_\_\_\_ Fax: ( ) \_\_\_\_\_

Email: \_\_\_\_\_

Additional Operator Contact:

Contact Name

Phone

Email

Luke Reddy

970-515-1292

luke.reddy@anadarko.com

COGCC INSPECTION SUMMARY:

FIR Document Number: 678301854

Inspection Date: 10/01/2018

FIR Submit Date: 10/01/2018

FIR Status: \_\_\_\_\_

Inspected Operator Information:

Company Name: KERR MCGEE OIL & GAS ONSHORE LP

Company Number: 47120

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-3779

LOCATION - Location ID: 302228

Location Name: FRANK-64N67W Number: 31NESE County: WELD

Qtrqr: NESE Sec: 31 Twp: 4N Range: 67W Meridian: 6

Latitude: 40.268140 Longitude: -104.925420

FACILITY - API Number: 05-123-00 Facility ID: 287126

Facility Name: FRANK Number: 9-31

Qtrqr: NESE Sec: 31 Twp: 4N Range: 67W Meridian: 6

Latitude: 40.268140 Longitude: -104.925420

CORRECTIVE ACTIONS:

1 CA# 119141

Corrective Action: Comply with Rule 603.f .

Date: 01/01/2019

Response: CA COMPLETED

Date of Completion: 10/18/2018

Operator  
Comment:

The wellhead was rebuilt 10/18. Wellwork was completed on 9/27. The piping and wellhead assembly is disassembled when wellwork is performed. After the wellwork is completed, the wellhead gets rebuilt when the next crew is available.

COGCC Decision: \_\_\_\_\_

COGCC  
Representative: \_\_\_\_\_

**OPERATOR COMMENT AND SUBMITTAL**

Comment: The wellhead was rebuilt 10/18. Wellwork was completed on 9/27. The piping and wellhead assembly is disassembled when wellwork is performed. After the wellwork is completed, the wellhead gets rebuilt when the next crew is available.

I hereby certify that the statements made in this form are, to the best of my knowledge, true, correct, and complete.

Print Name: Luke Reddy

Signed: \_\_\_\_\_

Title: Regulatory Specialist

Date: 11/1/2018 8:32:39 AM

**ATTACHMENT LIST**

View Attachments in Imaged Documents on COGCC website (<http://ogccweblink.state.co.us/>) - Search by Document Number.

<b><u>Document Number</u></b>	<b><u>Description</u></b>
-------------------------------	---------------------------

--	--

Total Attach: 0 Files