

**Inspection Photo
Jolley KP 514-17
API # 045-17678
Inspection # 689302235**



0/30/18

Location Photo #1



0/30/18

Location Photo #2



**Inspection Photo
Jolley KP 514-17
API # 045-17678
Inspection # 689302235**



Location Photo #3



Location Photo #4, Unmarked flow line.

**Inspection Photo
Jolley KP 514-17
API # 045-17678
Inspection # 689302235**



Location Photo #5, Mechanical condition of tank fitting.



Location Photo #6, Missing capacity on all tanks

**Inspection Photo
Jolley KP 514-17
API # 045-17678
Inspection # 689302235**



Location Photo #7, Missing capacity on all tanks



Location Photo #8, unused equipment.