

# Inspection Photos

11/1/2018

Operator: FRITZLER RESOURCES INC - 31257

Location ID: 316908

Inspection Doc. Number: 682504077

Washington County, CO

Aaron Trujillo  
NE Reclamation Specialist  
COGCC



**Photo 1:** Photo of sign at well

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 2:** Photo taken from the south end of the pump unit, facing west. Photo shows unused equipment being stored on location.



**Photo 3:** Photo taken from the south end of the pump unit, facing west. Photo shows unused equipment being stored on location.



**Photo 4:** Photo taken from the south end of the pump unit, facing west. Photo shows unused equipment being stored on location.



**Photo 5:** Photo taken from the west end of the pump unit, facing west. Photo shows unused equipment being stored on location.



**Photo 6:** Photo taken from the northwest end of the location, facing west. Photo shows unused equipment being stored on location.

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 7:** Photo taken from the northwest end of the location, facing east. Photo shows vegetation over the interim areas.



**Photo 8:** Photo taken from the northwest end of the location, facing south. Photo shows vegetation over the interim areas, as well as unused equipment being stored on location.

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 9:** Photo taken from the north end of the pump unit, facing east. Photo shows unused equipment being stored on location.

Inspection Photos  
Operator: FRITZLER RESOURCES INC - 31257  
Location ID: 316908



**Photo 10:** Photo taken from the southeast end of the location, facing north. Photo shows vegetation over the interim areas.



**Photo 11:** Photo taken from the southeast end of the location, facing west. Photo shows vegetation over the interim areas.



**Photo 12:** Photo taken from the southeast end of the location, facing north. Photo shows anchor without proper marking.



**Photo 13:** Photo taken from the northwest corner of the pits, facing east.



**Photo 14:** Photo taken from the northwest corner of the pits, facing south.



**Photo 15:** Photo taken from the north end of the pits. Photo shows what appears to be Canada thistle rosettes on the pit. Some plant appear to have matured and have seeded out. This is a Colorado State listed noxious weed and needs to be managed.



**Photo 16:** Photo taken from the north of the tanks, facing west. Photo shows “landfarm” area under remediation project #8509. Vegetation seen in photo is predominantly undesirable weedy plant species. Mowing operations appear to have been conducted.



**Photo 17:** Photo taken from “landfarm” area. Photo shows vegetation predominantly undesirable weedy plant species. Photo also shows what appears to be Canada thistle rosettes (green plants).



**Photo 18:** Photo taken from the northeast end of the pit facing east. Photo shows produced water being discharging from the base of the pit.



**Photo 19:** Photo taken from the northeast end of the pit, facing north. Photo shows area where water was observed actively spilling from the base of the pit.



**Photo 20:** Photo taken from the east of the pit facing west. Photo shows produced water being discharging from the base of the pit.



**Photo 21:** Photo taken from the east of the pit facing north. Photo shows produced water being discharging from the base of the pit.



**Photo 22:** Photo taken from the northeast end of the pit. Operator arrived on site at 14:22 hours and began to dig at the sidewall of the pit. Photo shows the area of the pit currently leaking.



**Photo 23:** Continued from photo 22.



**Photo 24:** Photo of back-hoe brought to site to commence repairs on pit.