



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

API# 007-06120
SPILL# 457801
LOC# 320854
Doc# 2303202
Date: 9/24/2018

C 970.903.4072

P.O. Box 4453 Durango, Colorado 81302

jimo.hughes@state.co.us | www.colorado.gov/cogcc

----- Forwarded message -----

From: **Brittany Hall** <bhall@envirotech-inc.com>

Date: Mon, Sep 24, 2018 at 3:09 PM

Subject: Alamosa Drilling Chavez #1 Water Analytical Results

To: jimo.hughes@state.co.us <jimo.hughes@state.co.us>

Jim,

Attached are the analytical results for the three (3) water samples collected from the Chavez #1 site as well as a few pictures for your reference. Please let me know if you have any suggestions on how the state would like to proceed after reviewing the information. IMG_0193 is the western wall, IMG_0191 is the excavation after we finished up on Friday, September 14, and IMG_0225 is what the excavation looked like on September 19. We also potholed approximately 20 feet and 40 feet to the west of the excavation in order to delineate the contamination. We did run into soil that had a hydrocarbon odor in the bottom of both potholes.

Thank you,

Brittany Hall

Environmental Field Technician

Envirotech, Inc. | 5796 US Highway 64 | Farmington, NM 87401

505.632.0615 Office | 505.632.1865 Fax | 505.947.9179 Cell

2C8D5D52-9E96-4BAE-94E6-19E7F898691A@local

<http://envirotech-inc.com/>

4 attachments



IMG_0193.JPG
2886K



IMG_0191.JPG
5223K



IMG_0225.jpg
1222K

 **P809029 Envirotech2_v15 FINAL 09 19 18 1548.pdf**
471K