

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #1 – Pit facility sign located on north side of pit.



Photo #2 – View of north side of pit from NE corner. Note that bird netting was absent from pit and free product was present on top of pit fluids in NE corner (red arrow). Operator was notified about oil on pit via phone on inspection date.

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #3 – Patches observed in liner on east side of pit. Liner has been repaired in response to previous Field Inspection Report (doc #681701069).



Photo #4 – Additional patch observed in liner on east side of pit. Liner has been repaired in response to previous Field Inspection Report (doc #681701069).

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #5 – Patches observed in SE corner of pit liner. Liner has been repaired in response to previous Field Inspection Report (doc #681701069).



Photo #6 – Ratchet strap on south end of pit sagging into pit contents.

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #7 – View of bird netting from SW corner of pit. Operator indicated via 11/1/2018 phone call that netting had been removed for the winter to prevent damage caused by snow accumulation, per an agreement between the operator and CPW.



Photo #8 – Additional patch observed in liner on west side of pit.

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #9 – Hole in NW corner of pit fence.



Photo #10 – Additional hole in NW corner of pit fence.

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #11 – Sandbag beneath inlet hose in NW corner of pit has been repositioned to prevent direct contact between hammer union and pit liner.



Photo #12 – Second inlet hose in NW corner of pit has been repositioned to prevent direct contact between metal fittings and pit liner.



Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #13 – Tear in pit liner observed in SE corner of pit, along anchor trench.



Photo #14 – Tear in pit liner observed in SW corner of pit, along anchor trench.

Inspection Photos

Location Name: Pond G Centralized E&P Waste Management Facility

Facility ID: #437578 Pit ID: #414402

Inspection Date: November 1, 2018



Photo #15 – Contractors were on location to install tank insulation on inspection date.