

FORM
INSPRev
X/15State of Colorado
Oil and Gas Conservation Commission1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

10/30/2018

Submitted Date:

11/01/2018

Document Number:

692400264

FIELD INSPECTION FORM

Loc ID 436676	Inspector Name: Colby, Lou	On-Site Inspection <input type="checkbox"/>	2A Doc Num: _____	Status Summary: <input type="checkbox"/> THIS IS A FOLLOW UP INSPECTION <input checked="" type="checkbox"/> FOLLOW UP INSPECTION REQUIRED <input type="checkbox"/> NO FOLLOW UP INSPECTION REQUIRED Findings: 6 Number of Comments 1 Number of Corrective Actions <input checked="" type="checkbox"/> Corrective Action Response Requested			
Operator Information: OGCC Operator Number: 10598 Name of Operator: SANDRIDGE EXPLORATION & PRODUCTION LLC Address: 123 ROBERT S KERR AVE City: OKLAHOMA CITY State: OK Zip: 73102				ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE			
Contact Information:							
Contact Name	Phone	Email	Comment				
		sandridgeenvironmental@san dridgeenergy.com					
Inspected Facilities:							
Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436676	LOCATION	AC	04/06/2014		-	Surprise Central Facility	CI
General Comment:							
This is a Post Construction and Stormwater Inspection. Form 42: NOTICE OF CONSTRUCTION: was Filed for this Site, Start Date 7/30/18. Conditions at time of Inspection were low overcast skies, spitting snow at 32 degrees F. Elevation at Site is 8,265 ft.							
Location Construction							
Location ID: 436676		CDP: _____					
Comment:	Construction of Location appears complete, equipment has been & is being installed. This site has no associated Wells and is an expansion of an existing location, equipment of which will service neighboring Producing sites. Silt Fence was installed as perimeter control.						
Corrective Action:							Date: _____
Form 2A COAs:							
Comment:							
Corrective Action:							Date: _____
Wildlife BMPs:							
Comment:	This Location is in a Sensitive Wildlife Habitat; Greater Sage Grouse.						
Corrective Action:							Date: _____
Stormwater:							
Erosion BMPs	Present	Other BMPs				Present	

BERMS	Yes		
Comments: Erosion BMPs: <input type="text"/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

SILT FENCES	Yes		
Comments: Erosion BMPs: <input type="text" value="Silt fence needs repair on North & West sides of Location."/>			
Other BMPs: <input type="text"/>			
Corrective Action: <input type="text" value="Install or repair required BMPs per Rule 1002.f."/>			Date: <input type="text" value="11/15/2018"/>

	Yes		
Comments: Erosion BMPs: <input type="text" value="Wier installed on North perimeter of Pad."/>			
Other BMPs: <input type="text"/>			
Corrective Action: _____			Date: _____

Comment:

Corrective Action: **Date:** _____

On Site Inspection (305):

Surface Owner Contact Information:

Name: _____ Address: _____
 Phone Number: _____ Cell Phone: _____

Operator Rep. Contact Information:

Landman Name: _____ Phone Number: _____
 Date Onsite Request Received: _____ Date of Rule 306 Consultation: _____
 Request LGD Attendance: _____

LGD Contact Information:

Name: _____ Phone Number: _____ Agreed to Attend: _____

Summary of Landowner Issues:

Summary of Operator Response to Landowner Issues:

Onsite Inspection Memorandum Summarizing Discussions at Inspection as Attachment:

Inspected FacilitiesFacility ID: 436676 Type: LOCATION API Number: - Status: AC Insp. Status: CI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
692400265	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4632014