

Inspection Photos

Operator: WPX Energy

API: 05-067-05752

Date: 10/24/2018



Photo 1. View of the project area from southern edge facing west toward the well head marker (in the background). Revegetation is patchy within the reclamation areas with grasses such as crested wheatgrass (*Agropyron cristatum*), western wheatgrass (*Pascopyrum smithii*), as well as rubber rabbitbrush (*Chrysothamnus nauseosus*).



Photo 2. View of the project area from the southwestern edge facing northeastward.



Photo 3. View of the southern project area from the southwestern edge facing eastward.



Photo 4. View of anchor marker in place and debris that needs to be removed.



Photo 5. View of the beginning of the access road, with poor revegetation.



Photo 6. View of the beginning of Transect 1, within the project area facing eastward.



Photo 7. Birdseye view of vegetation at the mid-point of Transect 1.



Photo 8. View of the beginning of Transect 2, within the reference area facing southward.



Photo 9. Birdseye view of vegetation at the mid-point of Transect 2, within the reference area.