

**FORM  
INSP**

Rev  
X/15

**State of Colorado  
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

10/30/2018

Submitted Date:

10/30/2018

Document Number:

679701571

**FIELD INSPECTION FORM**

Loc ID 315237 Inspector Name: Moran, Rick On-Site Inspection  2A Doc Num: \_\_\_\_\_

**Status Summary:**

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

**Operator Information:**

OGCC Operator Number: 74740  
Name of Operator: RIO MESA RESOURCES INC  
Address: P.O. BOX 984  
City: RANGELY State: CO Zip: 81648

**Findings:**

- 4 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
Kellerby, Shaun	970-712-1248	shaun.kellerby@state.co.us	
Hayes, Mike	970-620-2257	hayespetro@centurytel.net	
Pesicka, Conor	970-415-0789	conor.pesicka@state.co.us	
COGCC, Engineering	303-894-2100	dnr_cogccEngineering@state.co.us	
Waldron, Emily		emily.waldron@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230455	WELL	SI	04/01/2014	OW	103-08118	PHILLIPS-NEWTON 2-1	SI

**General Comment:**

[Follow up inspection to document 689500743](#)

Location			
<b>Lease Road:</b>			
Type	Access		
comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	970-675-8491		
Corrective Action:			Date: _____
<b>Good Housekeeping:</b>			
Type	TRASH		
Comment:			
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
<b>Spills:</b>			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
<b>Equipment:</b>			
Type: Vertical Separator	# 1		corrective date
Comment:			
Corrective Action:			Date:
Type: Pump Jack	# 1		
Comment:			
Corrective Action:			Date:
Type: Deadman # & Marked	# 4		
Comment:			

Corrective Action:	Date:
--------------------	-------

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	2	400 BBLs	STEEL AST		40.078314,-108.810755

Comment:	Date:
Corrective Action:	Date:

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Inadequate	Walls Sufficient	Base Sufficient	Inadequate
Comment: <span style="color:blue">Inadequate berms around tank(s). (Berm on west side has inadequate height).</span>				
Corrective Action: <span style="color:red">Repair or install berms or other secondary containment devices per Rule 605.a.(4).</span>				Date: <u>11/30/2018</u>

**Venting:**

Yes/No	NO	Date:
Comment:		
Corrective Action:		Date:

**Flaring:**

Type		Date:
Comment:		
Corrective Action:		Date:

**Inspected Facilities**

Facility ID: 230455 Type: WELL API Number: 103-08118 Status: SI Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: Last recorded production July 2014. No record of MIT.  
No current MIT on record or delinquent as required by Rule 326

Corrective Action: Contact [dnr\\_cogccengineering@state.co.us](mailto:dnr_cogccengineering@state.co.us) with resolution plan. Date: 05/13/2018

**Reclamation - Storm Water - Pit**

**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment

Comment:

Corrective Action:

Date: \_\_\_\_\_

**Pits:**     NO SURFACE INDICATION OF PIT

Type: Blowdown                      Lined: NO                      Pit ID:                      Lat: 40.078380                      Long: -108.811617

Reference Point: \_\_\_\_\_                      Other: \_\_\_\_\_                      Length: \_\_\_\_\_                      Width: \_\_\_\_\_

**Lining:**

Liner Type: \_\_\_\_\_                      Liner Condition: \_\_\_\_\_

Comment:

Corrective Action

Date:

**Fencing:**

Fencing Type: Wildlife                      Fencing Condition: Adequate

Comment:

Corrective Action

Date:

**Netting:**

Netting Type: Mesh                      Netting Condition: Good

Comment:

Corrective Action

Date:

Anchor Trench Present: \_\_\_\_\_                      Oil Accumulation: NO                      2+ feet Freeboard: YES

Comment:

Corrective Action

Date:

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
401817633	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627047">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627047</a>
679701572	inspection 679701571 photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627037">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=4627037</a>